

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

MSIG INSURANCE (SINGAPORE) PTE LTD
 4 SHENTON WAY #21-01
 SGX CENTRE 2 SINGAPORE 068807

Attention : Motor Claim Department
 Contact : 6827 7888

Estimate : TP24/040

Date : 07/11/2024
 Vehicle Num. : SKA 671C
 Make/Model : VOLKSWAGEN GOLF-2019
 Chassis/Eng# : WVVZZZAUZKW137305/CZCC01877
 Accident Date : 07/11/2024
 Claim No. :
 Reference : LYB/SKA671C/MSIG/TP/sl
 Policy No. :

Not Authorized 108
 1/1/2024 @ 5:50 PM 6400h
 Messing After Paint
 5 days ~~4 days~~

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE	150.101N	2,200.75
2.	1	REAR TAILGATE RUBBER	Cur	300.21
3.	2	REAR TAILGATE ABSORBER	129.20	258.40
4.	1	REAR TAILGATE LOCK /UPPER	Ad	280.52
5.	1	REAR TAILGATE LOCK/ LOWER	Ad	280.52
6.	1	REAR TAILGATE INNER TRIM BOARD	Ad	500.54
7.	2	REAR TAILGATE RUBBER STOPPER/ROUND	38.20	76.40
8.	1	REAR BUMPER	Bur	1,477.32
9.	1	REAR BUMPER LIP SPOILER	Ad	400.54
10.	2	REAR BUMPER REFLECTOR	25.00	50.00
11.	2	REAR BUMPER CHROME (SIDE)	90.00	180.00
12.	1	REAR BUMPER REINFORCEMENT	Ad	588.75
13.	1	REAR BUMPER RETAINER (CENTRE)	Cur	296.20
14.	2	REAR BUMPER SIDE RETAINER	90.97	181.94
15.	1	REAR BUMPER TOWING COVER	Ad	45.60
16.	1	REAR SPARE TYRE PANEL	Ad	988.70
17.	1	REAR SPARE TYRE PANEL INSULATOR PADDING	Ad	200.00
18.	1	REAR SPARE TYRE TRIM BOARD	Ad	500.50
19.	1	REAR TAILEND PANEL	Ad	999.54
20.	1	REAR TAILEND TOP GARNISH	Cur	300.47
21.	2	REAR TAILLAMP	688.98	1,377.96
22.	2	REAR REFLECTOR	600.54	1,201.08
23.	2	REAR REFLECTOR SIDE COVER	68.90	137.80
24.	1	REAR WIPER MOTOR	Ad	688.56

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

MSIG INSURANCE (SINGAPORE) PTE LTD
 4 SHENTON WAY #21-01
 SGX CENTRE 2 SINGAPORE 068807

Attention : Motor Claim Department
 Contact : 6827 7888

Estimate : TP24/040

Date : 07/11/2024
 Vehicle Num. : SKA 671C
 Make/Model : VOLKSWAGEN GOLF-2019
 Chassis/Eng# : WVVZZZAUZKW137305/CZCC01877
 Accident Date : 07/11/2024
 Claim No. :
 Reference : LYB/SKA671C/MSIG/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	REAR WIPER ARM		129.50 X
26.	1	REAR WIPER BLADE		68.90 X
27.	2	REAR NO PLATE LAMP	55.90	111.80 X
List Total S\$:				13,822.50
10.00% Discount S\$:				1,382.25
				12,440.25
SPECIAL NETT ITEMS :				
1.	8	REAR TAILGATE INNER TRIM BOARD WHITE CLIPS	8.00	64.00 X
2.	1	REAR SPARE TYRE PANEL SEALANT		120.00 X
3.	1	REAR TAILEND PANEL THEROSTAT SEALANT		64.20 X
4.	5	REAR TAILEND TOP GARNISH CLIPS	8.00	40.00 X
5.	1	REAR EMBLEM 'VW'		62.30
6.	1	REAR EMBLEM 'GOLF'		86.30
7.	1	REAR NO PLATE (EMBOSS)		35.00
8.	1	REAR NO PLATE HOLDER		25.00
9.	2/	REAR REVERSE SENSOR	280.00	560.00 X
10.	4	REAR REVERSE SENSOR HOUSING	35.00	140.00
11.	1	REAR W/SCREEN INNER SEAL		80.00 30.50
12.	1	REAR W/SCREEN SEALANT		80.00 40.50
Special Nett Total S\$:				1,356.80
LABOUR :				120.00 30/
TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS				

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724

E-Mail : limyewboo@singnet.com.sg

Website : www.limyewboo.com.sg

Buss. Reg. No. : 20051400L

MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY #21-01
SGX CENTRE 2 SINGAPORE 068807

Attention : Motor Claim Department

Contact : 6827 7888

Estimate : TP24/040

Date : 07/11/2024
Vehicle Num. : SKA 671C
Make/Model : VOLKSWAGEN GOLF-2019
Chassis/Eng# : WWWZZZAUZKW137305/CZCC01877
Accident Date : 07/11/2024
Claim No. :
Reference : LYB/SKA671C/MSIG/TP/sl
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CHECK WATER SEEPAGE	60.00	201
		TO CHECK REAR WIRING FUNCTION	35.00	201
		LABOUR TO REMOVE REAR W/S	180.00	1201
		LABOUR TO CHECK, STRAIGHTEN AFFECTED REAR SILENCER	150.00	X
		TO RE-SET ABS SYSTEM & EARSE REGISTERED FAULT	150.00	X
		TO REMOVE & REFIX REAR INTERIOR FITTINGS, TRIMING IN ORDER TO FACILIATE REPAIR JOB	250.00	X
		TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS	80.00	601
		TO REPAIR, PANEL BEAT, STRAIGHTEN ON AFFECTED AREA, CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE ABOVE PARTS	1,800.00	5001
		TO PUTTY, PRIMER & SPRAY PAINT ON REAR TAILGATE, REAR SPARE TYRE PANEL, TAILEND PANEL, REAR BUMPER & AFFECTED LEFT & REAR FENDER USING 2K PAINT	1,800.00	6001
		Labour Total S\$:		4,625.00

E. & O.E.

Total S\$: 18,422.05

=====

for LIM YEW BOO SPRAY PAINT CO.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: