

ASS. REC. BY:

REF:

1CS / CS/ICS24110186/Kvp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. MPU24B00022900

Claims No. DMPU2400066H/ST/LLA

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14 days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Midnight call

25/4/25

Final fig \$48,694 confirmed by email (Red 11,796, 20%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair: 14

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

: Fuel

: Others

TOTAL

Veh No:

SNL 4789C

Yr Regn:

08, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Noah

c.c

Wagon 1797

Colour

M. P. white

A/C:

Insured / Std / NI / NA

Sp. Reading

136442

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

EWR 90. 00091172

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

215/55ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pleasant

Front

Rear

R/Bal.

8

mm

R/Bal.

9

mm

L/Bal.

8

mm

L/Bal.

9

mm

D.O.A.

29/10/24

D.O.I.

9/12/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	669J

Vehicle Details

Vehicle No.:	SNL4789C
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID S-Z
Primary Colour:	White
Manufacturing Year:	2023
Engine No.:	2ZR2V20768
Chassis No.:	ZWR900091172
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$30,810.00
Original Registration Date:	15 Aug 2023
First Registration Date:	15 Aug 2023
Transfer Count:	0
Actual ARF Paid:	\$20,134.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2033
PARF Rebate Amount:	\$15,100.00

Intended COE Rebate Details

COE Expiry Date:	14 Aug 2033
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$121,000.00
COE Rebate Amount:	\$105,256.00
Total Rebate Amount:	\$120,356.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 02 Dec 2024

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	29/10/2024 13:15 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	29/10/2024 03:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE Towards Changi , Before Jln Eunos Exit
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNL4789C
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	MUHAMMED FAIROL BIN ABDULLAH
NRIC No	S8947669J
Email Address	muhdfaird89@gmail.com
Mobile Phone No	(Phone) +65-87535499
Alternative Phone No	+65-90105255

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Noah
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	1797
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Policy Number / Cover Note Number	MPU24B00022900

DRIVER

Name of Driver	MUHAMMED FAIROL BIN ABDULLAH
NRIC No	S8947669J
Date Of Birth	04/07/1989
Occupation	Outdoor
Driving Pass Date	12/03/2010
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	14 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-87535499
Alt. Phone Number	+65-90105255
Email Address	muhdfaird89@gmail.com
Address	APT BLK 41 TELOK BLANGAH RISE #05-375
Address complement	-
Postcode	090041
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	Unknown
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Please Refer To Accident Sketch Plan

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XF6886E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	THANASHKOOTI PANNER
Passport No/FIN	F4513977T
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

Describe Circumstances of the Accident

Veh A SNL 4789 C

Veh B XF6886E

While I was driving my car, I experience a total blackout and suddenly saw a stationary truck in front of me and I got no space to avoid. hence I hit the rear of the truck (Veh B).

Declaration

We declare the foregoing particulars are true in every respect.

 29/10/24
 Policyholder's Signature / Date &
 Time 12:00 pm

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel

SKETCH PLAN

Veh A: SNL4769C
Veh B: x12266E

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*) I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

 29/10/24
Policyholder's Signature / Date & Time
12:08pm

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



Estimated Cost of Repair

Attention To : **ECICS LIMITED**
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/122024/7903
Date : 02-12-2024
Accident Date : 29-10-2024

Vehicle Details

Make & Model : Toyota NOAH HYBRID S-Z
Chassis No : ZWR900091172
Registration No : SNL4789C

NOT Withheld
Recovery B4 pain
14 days
Ex @ 2000p

S/N	Description	Qty	Amount (S\$)	
1	FRONT BONNET (ORDER)	1.00	<i>h</i> \$850.00	✓
2	BONNET RH HINGE	1.00	<i>h</i> \$50.00	✓
3	BONNET LH HINGE	1.00	<i>h</i> \$50.00	✓
4	BONNET INSULATOR	1.00	<i>mit</i> \$170.00	✓
5	BONNET MOULDING	1.00	<i>mit</i> \$190.00	✓
6	BONNET LOCK	1.00	<i>h</i> \$70.00	✓
7	BONNET LOCK CABLE	1.00	<i>h</i> \$40.00	✓
8	BONNET STAND (ORDER)	1.00	<i>h</i> \$30.00	X
9	BONNET STAND CLIP (ORDER)	1.00	<i>mit</i> \$20.00	✓
10	RH HEADLAMP	1.00	<i>Bo</i> \$1,300.00	✓
11	LH HEADLAMP	1.00	<i>Bo</i> \$1,300.00	✓
12	FRONT GRILLE ASSY	1.00	<i>CM</i> \$1,100.00	✓
13	FRONT GRILLE EMBLEM	1.00	<i>mit</i> \$50.00	✓
14	FRONT RADAR (ORDER)	1.00	<i>nd</i> \$620.00	✓
15	FRONT LH BUMPER	1.00	<i>mg CM</i> \$250.00	✓
16	FRONT RH BUMPER	1.00	<i>CM</i> \$250.00	✓
17	FRONT BUMPER RH FOG LAMP	1.00	<i>mg CM</i> \$240.00	✓
18	FRONT BUMPER LH FOG LAMP	1.00	<i>u u</i> \$240.00	✓
19	FRONT BUMPER TOWING COVER	1.00	<i>mit</i> \$30.00	✓
20	FRONT RH BUMPER TOP SUPPORT BRACKET	1.00	<i>DI</i> \$70.00	✓
21	FRONT LH BUMPER TOP SUPPORT BRACKET	1.00	<i>DI</i> \$70.00	✓
22	FRONT BUMPER SPONGE (ORDER)	1.00	<i>CM</i> \$70.00	✓
23	FRONT BUMPER REINFORCEMENT (ORDER)	1.00	<i>B</i> \$290.00	✓
24	FRONT BUMPER REINFORCEMENT RH BRACKET (ORDER)	1.00	<i>B</i> \$140.00	✓
25	FRONT BUMPER REINFORCEMENT LH BRACKET (ORDER)	1.00	<i>B</i> \$140.00	✓
26	FRONT BUMPER LOWER BEAM	1.00	<i>R</i> \$200.00	X
27	FRONT BUMPER LOWER BEAM RH BRACKET	1.00	<i>R</i> \$70.00	X
28	FRONT BUMPER LOWER BEAM LH BRACKET	1.00	<i>R</i> \$70.00	X
29	FRONT BUMPER LOWER BEAM SPONGE	1.00	<i>CM</i> \$70.00	✓
30	FRONT BUMPER UNDER COVER	1.00	<i>CM</i> \$150.00	✓
31	FRONT BUMPER CLIPS	10.00	<i>h</i> \$20.00	✓

32	FRONT BUMPER LOWER SPOILER (ORDER)	1.00	CM	\$450.00	✓
33	FRONT BUMPER PARKING SENSOR	3 4.00	nd	\$720.00	2H
34	FRONT PARKING SENSOR WIRE HARNESS	1.00	Tr	\$150.00	✓
35	FRONT SUPPORT TOP PANEL	1.00	B	\$280.00	✓
36	FRONT SUPPORT RH SIDE PANEL	1.00	B	\$270.00	✓
37	FRONT SUPPORT LH SIDE PANEL	1.00	A	\$270.00	✓
38	FRONT SUPPORT LOWER PANEL	1.00	At	\$260.00	✓
39	BRACE PANEL	1.00	B	\$80.00	✓
40	AIRCON CONDENSOR (ORDER) (ORI)	1.00	Pu	\$800.00	✓
41	AIRCON DISCHARGE PIPE	1.00	nd	\$280.00	✓
42	RADIATOR (ORDER) (ORI)	1.00	Pu	\$920.00	✓
43	RADIATOR TOP HOSE	1.00	CM	\$40.00	✓
44	RADIATOR LOWER HOSE (ORDER)	1.00	CM	\$40.00	✓
45	RADIATOR RH SIDE GUIDE	1.00	CM	\$80.00	✓
46	RADIATOR LH SIDE GUIDE	1.00	CM	\$80.00	✓
47	RADIATOR FAN MOTOR ASSY (ORDER)	1.00	CM	\$750.00	✓
48	RADIATOR NECK FILLER	1.00	In	\$40.00	X
49	RADIATOR TOP BUSH	1.00	na	\$20.00	✓
50	RADIATOR LOWER BUSH	1.00	su	\$20.00	X
51	RADIATOR SPARE TANK (ORDER)	1.00	nd	\$130.00	✓
52	WIPER TANK (ORDER)	1.00	nd	\$100.00	✓
53	WIPER TANK NECK	1.00	nd	\$60.00	✓
54	WIPER TANK MOTOR	1.00	In	\$140.00	X
55	HORN	1.00	nd	\$60.00	✓
56	VEHICLE APPROACHING SPEAKER ASSEMBLY	1.00	CM	\$130.00	✓
57	RESONATOR (ORDER)	1.00	CM	\$120.00	✓
58	RESONATOR INTAKE HOSE	1.00	nd	\$130.00	✓
59	RESONATOR AIR DUCT	1.00	nd	\$60.00	✓
60	AIR CLEANER BOX (ORDER)	1.00	CM	\$450.00	✓
61	AIR CLEANER BOX HOSE (ORDER)	1.00	CM	\$60.00	✓
62	AIR CLEANER BOX SUPPORT BRACKET	1.00	Di	\$50.00	✓
63	INTAKE MANIFOLD (ORDER)	1.00	CM	\$350.00	✓
64	INTAKE MANIFOLD HEAT SHIELD	1.00	su	\$140.00	X
65	AIRCON COMPRESSOR (ORDER)	1.00	nd/Tu	\$2,800.00	✓
66	FUSE BOX @ LH (ORDER)	1.00	CM	\$140.00	✓
67	FUSE BOX LOWER COVER	1.00	CM	\$130.00	✓
68	BATTERY TRAY	1.00	CM	\$140.00	✓
69	BATTERY TRAY BRACKET	1.00	n	\$70.00	X
70	HYBRID INVERTER ASSY (W/ CONVERTER) (ORDER)	1.00	su	\$4,500.00	X
71	RH ENGINE MOUNTING (ORDER)	1.00	CM	\$420.00	✓
72	RH ENGINE MOUNTING BRACKET	1.00	su	\$280.00	X
73	LH ENGINE MOUNTING	1.00	su	\$130.00	X
74	GEARBOX MOUNTING (ORDER)	1.00	su	\$260.00	X
75	FRONT RH FENDER (ORDER)	1.00	Bu	\$400.00	✓

76	FRONT LH FENDER (ORDER)	1.00	Bu	\$400.00	✓
77	FRONT RH FENDER INNER SHIELD	1.00	CM	\$170.00	✓
78	FRONT LH FENDER INNER SHIELD	1.00	CM	\$170.00	✓
79	FRONT FENDER INNER SHIELD CLIPS	20.00	me	\$40.00	✓
80	FRONT RH FENDER GLASS (ORDER)	1.00	Sn	\$240.00	X
81	FRONT LH FENDER GLASS (ORDER)	1.00	Sn	\$240.00	X
82	FRONT RH FENDER GAP INSULATOR	1.00	me	\$110.00	✓
83	FRONT LH FENDER GAP INSULATOR	1.00	Sn	\$110.00	X
84	FRONT WINDSCREEN GLASS (ORDER)	1.00	CM	\$850.00	✓
85	FRONT WINDSCREEN GLASS RH MOULDING (ORDER)	1.00	GM	\$90.00	✓
86	FRONT WINDSCREEN GLASS LH MOULDING (ORDER)	1.00	Sn	\$90.00	X
87	WIPER GARNISH	1.00	Od	\$380.00	✓
88	WIPER GARNISH RH SIDE COVER	1.00	mi	\$40.00	✓
89	WIPER GARNISH LH SIDE COVER	1.00	mi	\$40.00	✓
90	DASHBOARD (ORDER)	1.00	CM	\$900.00	✓
91	STEERING WHEEL AIR BAG (ORDER)	1.00	Avon	\$1,800.00	✓
92	PASSENGER AIRBAG (ORDER)	1.00	u	\$2,200.00	✓
93	RH ROOF AIRBAG (ORDER)	1.00	u	\$2,100.00	✓
94	LH ROOF AIRBAG (ORDER)	1.00	u	\$2,100.00	✓
95	ROOF LINING (ORDER)	1.00	Deform	\$2,800.00	✓
96	FRONT RH SEAT BELT (ORDER)	1.00	Tu	\$800.00	✓
97	FRONT LH SEAT BELT (ORDER)	1.00	Tu	\$800.00	✓
98	AIRBAG ECU (ORDER)	1.00	me	\$1,700.00	✓
99	AIRBAG SENSOR	2.00	me	\$340.00	✓
				\$43,520.00	
				\$4,352.00	
				\$47,872.00	
100	FRONT NO. PLATE	1.00	mi	\$40.00	✓
101	FENDER GLASS GUM	1.00	nn	\$60.00	X
102	WINDSCREEN GUM	1.00	me	\$80.00	40Sn
103	COOLANT	1.00	me	\$80.00	40Sn
104	BATTERY	1.00	Od	\$180.00	50Sn
105	TO REMOVE AND REPLACE FENDER GLASS	1.00	nn	\$120.00	X
106	TO REFILL AIRCON GAS	1.00		\$150.00	100l
107	TO REMOVE AND REPLACE FRONT WINDSCREEN	1.00		\$180.00	120l
108	TO REMOVE AND REPLACE ROOF LINING	1.00		\$280.00	120l
109	TO RESET AIRBAG SYSTEM	1.00		\$280.00	200l
110	TO RESET HEADLAMP SYSTEM	1.00		\$280.00	160l
111	TO REMOVE AND REPLACE DASHBOARD	1.00		\$380.00	250l
112	TO RESET RADAR SYSTEM	1.00	nn	\$380.00	X
113	TO REMOVE AND REFIX ENGINE	1.00	250l	\$500.00	✓
114	TO REPAIR DAMAGES	1.00		\$1,800.00	900l

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Margin: 10%



115 TO SPRAY PAINTING

1.00

\$1,800.00

1200h

Subtotal w/o GST:

\$54,462.00

Issued by Raeny

This is a computer-generated document. No signature is required.



Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair (Supplementary)

Attention To : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/122024/7903
Date : 02-12-2024
Accident Date : 29-10-2024

Vehicle Details

Make & Model : Toyota NOAH HYBRID S-Z
Chassis No : ZWR900091172
Registration No : SNL4789C

S/N	Description	Qty	Amount (\$S)	
1	FRONT BUMPER RH FOG LAMP COVER	1.00	CM \$280.00	✓
2	FRONT BUMPER LH FOG LAMP COVER	1.00	CM \$280.00	✓
3	RESONATOR @LOWER	1.00	CM \$140.00	✓
4	ENGINE UNDER COVER	1.00	CM \$280.00	✓
5	ELECTRIC WATER PUMP	1.00	DD \$270.00	✓
6	FUSE BOX UPPER COVER #1	1.00	DD \$80.00	✓
7	FUSE BOX UPPER COVER #2	1.00	DD \$90.00	✓
8	RADIATOR LOWER GUIDE	1.00	CM \$80.00	✓
9	ENGINE UNDER COVER @LH	1.00	CM \$70.00	✓
10	INVERTER COOLING HOSE #1	1.00	CS \$60.00	✓
11	INVERTER COOLING HOSE #2	1.00	CS \$150.00	✓
12	INVERTER TANK	1.00	mg CM \$160.00	✓
13	INVERTER TANK HOSE	1.00	CS \$60.00	✓
14	FRONT WINDSCREEN TOP MOULDING	1.00	RE \$40.00	✓
15	HYBRID CONVERTOR +/- CABLE	1.00	DD \$480.00	✓
16	AIRCON SUCTION PIPE	1.00	RY \$250.00	✓
17	AIRCON RECEIVER PIPE	1.00	PR \$390.00	✓
18	THROTTLE BODY	1.00	DD \$920.00	✓
19	FRONT SUPPORT PANEL TOP COVER	1.00	CM \$100.00	✓

\$4,180.00

Margin: 10%

\$418.00

\$4,598.00

Subtotal w/o GST:

\$4,598.00

Issued by Elaine Lee

This is a computer-generated document. No signature is required.



Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair (Supplementary)

Attention To : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/122024/7903
Date : 02-12-2024
Accident Date : 29-10-2024

Vehicle Details

Make & Model : Toyota NOAH HYBRID S-Z
Chassis No : ZWR900091172
Registration No : SNL4789C

S/N	Description	Qty	Amount (S\$)
1	TAILGATE RH POWER GATE ABSORBER X	1.00	sn \$650.00 X
2	TAILGATE LH POWER GATE ABSORBER X	1.00	ln \$650.00 X
			\$1,300.00
Margin: 10%			\$130.00
			\$1,430.00
Subtotal w/o GST:			\$1,430.00

Parts : 36760 + 4180 (sup) = \$ 40,940 + 10% = \$45,034

SN : \$ 210

L : \$ 3680

GT : \$ 48,924

Issued by Vithyaa

This is a computer-generated document. No signature is required.

Estimated Cost of Repair

Attention To : **ECICS LIMITED**
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/122024/7903
Date : 02-12-2024
Accident Date : 29-10-2024

Vehicle Details

Make & Model : Toyota NOAH HYBRID S-Z
Chassis No : ZWR900091172
Registration No : SNL4789C

NOT Withheld
Recovery B4 pain
14 days *Ex B2000p*

S/N	Description	Qty	Amount (S\$)	
1	FRONT BONNET (ORDER)	1.00	<i>Al</i> \$850.00	✓
2	BONNET RH HINGE	1.00	<i>B1</i> \$50.00	✓
3	BONNET LH HINGE	1.00	<i>B1</i> \$50.00	✓
4	BONNET INSULATOR	1.00	<i>mit</i> \$170.00	✓
5	BONNET MOULDING	1.00	<i>mit</i> \$190.00	✓
6	BONNET LOCK	1.00	<i>B1</i> \$70.00	✓
7	BONNET LOCK CABLE	1.00	\$40.00	✓
8	BONNET STAND (ORDER)	1.00	<i>R</i> \$30.00	X
9	BONNET STAND CLIP (ORDER)	1.00	<i>mit</i> \$20.00	✓
10	RH HEADLAMP	1.00	<i>Bo</i> \$1,300.00	✓
11	LH HEADLAMP	1.00	<i>Bo</i> \$1,300.00	✓
12	FRONT GRILLE ASSY	1.00	<i>CM</i> \$1,100.00	✓
13	FRONT GRILLE EMBLEM	1.00	<i>mit</i> \$50.00	✓
14	FRONT RADAR (ORDER)	1.00	\$620.00	✓
15	FRONT LH BUMPER	1.00	<i>mg cm</i> \$250.00	✓
16	FRONT RH BUMPER	1.00	<i>cm</i> \$250.00	✓
17	FRONT BUMPER RH FOG LAMP	1.00	\$240.00	✓
18	FRONT BUMPER LH FOG LAMP	1.00	\$240.00	✓
19	FRONT BUMPER TOWING COVER	1.00	<i>mit</i> \$30.00	✓
20	FRONT RH BUMPER TOP SUPPORT BRACKET	1.00	<i>Di</i> \$70.00	✓
21	FRONT LH BUMPER TOP SUPPORT BRACKET	1.00	<i>Di</i> \$70.00	✓
22	FRONT BUMPER SPONGE (ORDER)	1.00	<i>CM</i> \$70.00	✓
23	FRONT BUMPER REINFORCEMENT (ORDER)	1.00	<i>B1</i> \$290.00	✓
24	FRONT BUMPER REINFORCEMENT RH BRACKET (ORDER)	1.00	<i>B1</i> \$140.00	✓
25	FRONT BUMPER REINFORCEMENT LH BRACKET (ORDER)	1.00	<i>B1</i> \$140.00	✓
26	FRONT BUMPER LOWER BEAM	1.00	\$200.00	✓
27	FRONT BUMPER LOWER BEAM RH BRACKET	1.00	\$70.00	✓
28	FRONT BUMPER LOWER BEAM LH BRACKET	1.00	\$70.00	✓
29	FRONT BUMPER LOWER BEAM SPONGE	1.00	<i>cm</i> \$70.00	✓
30	FRONT BUMPER UNDER COVER	1.00	\$150.00	✓
31	FRONT BUMPER CLIPS	10.00	<i>m</i> \$20.00	✓

32	FRONT BUMPER LOWER SPOILER (ORDER)	✓	1.00	\$450.00	?
33	FRONT BUMPER PARKING SENSOR		3 4.00	\$720.00	?
34	FRONT PARKING SENSOR WIRE HARNESS	✓	1.00	\$150.00	?
35	FRONT SUPPORT TOP PANEL		1.00	Bz \$280.00	✓
36	FRONT SUPPORT RH SIDE PANEL		1.00	Bz \$270.00	✓
37	FRONT SUPPORT LH SIDE PANEL		1.00	Az \$270.00	✓
38	FRONT SUPPORT LOWER PANEL	✓	1.00	\$260.00	?
39	BRACE PANEL		1.00	Bz \$80.00	✓
40	AIRCON CONDENSOR (ORDER) (ORI)		1.00	Pn \$800.00	✓
41	AIRCON DISCHARGE PIPE	✓	1.00	\$280.00	?
42	RADIATOR (ORDER) (ORI)	✓	1.00	\$920.00	?
43	RADIATOR TOP HOSE	✓	1.00	\$40.00	?
44	RADIATOR LOWER HOSE (ORDER)	✓	1.00	\$40.00	?
45	RADIATOR RH SIDE GUIDE		1.00	CM \$80.00	✓
46	RADIATOR LH SIDE GUIDE		1.00	CM \$80.00	✓
47	RADIATOR FAN MOTOR ASSY (ORDER)	✓	1.00	\$750.00	?
48	X RADIATOR NECK FILLER	X	1.00	\$40.00	?
49	RADIATOR TOP BUSH		1.00	na \$20.00	✓
50	X RADIATOR LOWER BUSH	X	1.00	\$20.00	?
51	RADIATOR SPARE TANK (ORDER)		1.00	DU \$130.00	✓
52	WIPER TANK (ORDER)		1.00	DU \$100.00	✓
53	WIPER TANK NECK	✓	1.00	\$60.00	?
54	X WIPER TANK MOTOR	X	1.00	\$140.00	?
55	HORN		1.00	DU \$60.00	✓
56	VEHICLE APPROACHING SPEAKER ASSEMBLY	✓	1.00	\$130.00	?
57	RESONATOR (ORDER)		1.00	CM \$120.00	✓
58	RESONATOR INTAKE HOSE		1.00	DU \$130.00	✓
59	RESONATOR AIR DUCT	✓	1.00	\$60.00	?
60	AIR CLEANER BOX (ORDER)		1.00	CM \$450.00	✓
61	AIR CLEANER BOX HOSE (ORDER)	✓	1.00	\$60.00	?
62	AIR CLEANER BOX SUPPORT BRACKET	✓	1.00	\$50.00	?
63	INTAKE MANIFOLD (ORDER)	✓	1.00	\$350.00	?
64	X INTAKE MANIFOLD HEAT SHIELD	X	1.00	\$140.00	?
65	AIRCON COMPRESSOR (ORDER)	✓	1.00	\$2,800.00	?
66	FUSE BOX @ LH (ORDER)	✓	1.00	\$140.00	?
67	FUSE BOX LOWER COVER	✓	1.00	\$130.00	?
68	BATTERY TRAY		1.00	CM \$140.00	✓
69	BATTERY TRAY BRACKET		1.00	n \$70.00	X
70	HYBRID INVERTER ASSY (W/ CONVERTER) (ORDER)		1.00	\$4,500.00	?
71	RH ENGINE MOUNTING (ORDER)	✓	1.00	\$420.00	?
72	X RH ENGINE MOUNTING BRACKET	X	1.00	\$280.00	?
73	X LH ENGINE MOUNTING	X	1.00	\$130.00	?
74	X GEARBOX MOUNTING (ORDER)	X	1.00	\$260.00	?
75	FRONT RH FENDER (ORDER)		1.00	Bu \$400.00	✓

76	FRONT LH FENDER (ORDER)		1.00	Bu	\$400.00	✓
77	FRONT RH FENDER INNER SHIELD	✓	1.00		\$170.00	7
78	FRONT LH FENDER INNER SHIELD	✓	1.00		\$170.00	7
79	FRONT FENDER INNER SHIELD CLIPS		20.00	me	\$40.00	✓
80	X FRONT RH FENDER GLASS (ORDER)	X	1.00		\$240.00	7
81	X FRONT LH FENDER GLASS (ORDER)	X	1.00		\$240.00	7
82	FRONT RH FENDER GAP INSULATOR	✓	1.00		\$110.00	7
83	X FRONT LH FENDER GAP INSULATOR	X	1.00		\$110.00	7
84	FRONT WINDSCREEN GLASS (ORDER)		1.00	CM	\$850.00	✓
85	FRONT WINDSCREEN GLASS RH MOULDING (ORDER)		1.00	GM	\$90.00	✓
86	FRONT WINDSCREEN GLASS LH MOULDING (ORDER)		1.00	SH	\$90.00	X
87	WIPER GARNISH		1.00	Od	\$380.00	✓
88	WIPER GARNISH RH SIDE COVER		1.00	mi	\$40.00	✓
89	WIPER GARNISH LH SIDE COVER		1.00	mi	\$40.00	✓
90	DASHBOARD (ORDER)		1.00	CM	\$900.00	✓
91	STEERING WHEEL AIR BAG (ORDER)		1.00	Bury	\$1,800.00	✓
92	PASSENGER AIRBAG (ORDER)		1.00	u	\$2,200.00	✓
93	RH ROOF AIRBAG (ORDER)		1.00	u	\$2,100.00	✓
94	LH ROOF AIRBAG (ORDER)		1.00	u	\$2,100.00	✓
95	ROOF LINING (ORDER)		1.00	Defon	\$2,800.00	✓
96	FRONT RH SEAT BELT (ORDER)		1.00	Tr	\$800.00	✓
97	FRONT LH SEAT BELT (ORDER)		1.00	Tr	\$800.00	✓
98	AIRBAG ECU (ORDER)		1.00	me	\$1,700.00	✓
99	AIRBAG SENSOR		2.00	me	\$340.00	✓

\$43,520.00

Margin: 10%

\$4,352.00

\$47,872.00

100	FRONT NO. PLATE		1.00	mi's	\$40.00	✓
101	FENDER GLASS GUM		1.00		\$60.00	7
102	WINDSCREEN GUM		1.00	me	\$80.00	40JA
103	COOLANT		1.00	me	\$80.00	40JA
104	BATTERY		1.00	Ad	\$180.00	50JA
105	TO REMOVE AND REPLACE FENDER GLASS		1.00		\$120.00	7
106	TO REFILL AIRCON GAS		1.00		\$150.00	100L
107	TO REMOVE AND REPLACE FRONT WINDSCREEN		1.00		\$180.00	120L
108	TO REMOVE AND REPLACE ROOF LINING		1.00		\$280.00	120L
109	TO RESET AIRBAG SYSTEM		1.00		\$280.00	200L
110	TO RESET HEADLAMP SYSTEM		1.00		\$280.00	160L
111	TO REMOVE AND REPLACE DASHBOARD		1.00		\$380.00	250L
112	TO RESET RADAR SYSTEM		1.00		\$380.00	7
113	TO REMOVE AND REFIX ENGINE		1.00	250L	\$500.00	7
114	TO REPAIR DAMAGES		1.00		\$1,800.00	900L



115 TO SPRAY PAINTING

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

1.00

\$1,800.00 *1200*

Subtotal w/o GST:

\$54,462.00

Issued by Raeny

This is a computer-generated document. No signature is required.

		SNL4789C			
		TOYOTA NOAH 2023			
		ZWR90-0091172			
	DATE IN	29.10.2024			
	MILLAGE	TOW IN			
		SUPPLEMENTARY			
1	1pc	Front bumper RH fog lamp cover			CRA ✓
2	1pc	Front bumper LH fog lamp cover			CRA ✓
3	1pc	Resonator @ Lower			CM ✓
4	1pc	Engine under cover			CM ✓
5	1pc	Electric Water pump			nd ✓
6	1pc	Fuse box upper cover			nd ✓
7	1pc	Fuse box upper cover			nd ✓
8	1pc	Radiator lower guide			CM ✓
9	1pc	Engine under cover @ LH			CM ✓
10	1pc	Inverter cooling hose long			wt ✓
11	1pc	Inverter cooling hose short			wt ✓
12	1pc	Inverter tank spare			nd ✓
13	1pc	Inverter tank hose			wt ✓
14	1pc	Front windscreen top moulding			nd ✓
15	1pc	Hybrid convertor +/- cable			nd ✓
16	1pc	Aircon suction pipe			nd ✓
17	1pc	Aircon receiver pipe			nd ✓
18	1pc	Throttle body			nd ✓
19	1pc	Front support panel top cover			CRA ✓

Veron Chen (LKKAuto)

From: Celestia Woo Tze Yinn <celestiawoo@vinsautogroup.com.sg>
Sent: Saturday, 15 March 2025 9:49 AM
To: Veron Chen (LKKAuto)
Cc: SUR; Vin's Claims; Kenneth Kong (LKKAuto)
Subject: Re: SNL4789C - ECICS OD - DOA: 29/10/2024 - FINALIZATION
Attachments: SNL4789C - SUPPLIER INVOICE.pdf; SNL4789C - MECOR.pdf

Hi Veron.

Good day.

Kindly refer to the attached Supplier Invoice and MECOR.

Parts:\$36760+4180(SUP) +10% =\$45034
SN: \$210
L: \$3680
GT: \$48924

Can we finalize @ \$48924(B4 GST) at PP basis with 14 working days?

Do let me know if you need anything for finalization.

Thank you.

Best Regards,
Celestia Woo
Claims Officer
Vin's Automotive Group
Omotenashi | Kaizen



M: 8076 1449
O: 6453 2121 Ext: 2211
F: 6456 5068
E: celestiawoo@vinsautogroup.com.sg
W: <https://vinsautogroup.com.sg/>

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, March 11, 2025 15:52
To: Celestia Woo Tze Yinn <celestiawoo@vinsautogroup.com.sg>
Cc: SUR <sur@lkkauto.com>; Vin's Claims <claims@vinsautogroup.com.sg>; Kenneth Kong (LKKAuto)



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
60 JALAN LAM HUAT CARROS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625226 / 62569633 FAX: 63626977



Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW UEN : 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9639



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 979

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL : 64532121 VINCENT FAX : 64599795 ACC/64590433
ATTN : 4532121

TAX INVOICE : AR202501-09459
DATE : 02/01/2025
CUSTOMER ID : VIN002
VEH REG. NO. : SNL4789C
TERMS : 30 DAYS
PO NO. :

PAGE NO. : Page 1 of 8
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	53301-V1010 ZWR90-NOAH	FRT BONNET	CC CC12-E-04C	1	850.00	850.00
2.	53410-V1010 ZWR90	FRT BONNET HINGE RH	CC CC12-P-02B8	1	50.00	50.00
3.	53420-V1010 ZWR90	FRT BONNET HINGE LH	CC CC12-H-1B11	1	50.00	50.00
4.	53341-V1010 ZWR90	FRT BONNET INSULATOR	CC C13-J1-6B	1	170.00	170.00
5.	75770-V1010 ZWR90-NOAH	FRT BONNET GARNISH	CC C13-K1-9AA	1	190.00	190.00
6.	53510-V1010 ZWR90-NOAH	FRT BONNET LOCK	CC C14-H1-3D5	1	70.00	70.00
7.	53630-V1010 ZWR90	FRT BONNET CABLE	CC NEW	1	40.00	40.00
8.	55729-V1010 ZWR90	FRT BONNET STAY HOLDER	CC NEW	1	20.00	20.00
9.	81110-V1021 ZWR90	HEAD LAMP RH	CC CC12-H-04D	1	1300.00	1,300.00
10.	81150-V1021 ZWR90	HEAD LAMP LH	CC CC12-B-04D	1	1300.00	1,300.00
11.	53101-V1020 ZWR90-NOAH	FRT GRILLE	CC C13-L1-8A	1	1100.00	1,100.00
12.	75301-V1020 ZWR90	FRT EMBLEM	CC CC12-H-01B4	1	50.00	50.00
13.	88210-78020 AAZH25 ZWR90 MXP110	SENSOR ASSY, MILLIMETER WAVE RADAR	CC CC12-M-02B	1	620.00	620.00
14.	52113-V1901 ZWR90	FRT BUMPER LH	CC CC12-H-10B	1	250.00	250.00

CONTINUE NEXT PAGE

[P] 21/01/2025 13:11:09

Goods Sold are not refundable for Cash.



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
60 JALAN LAM HUAT CARPOS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625226 / 62569633 FAX: 63626977



Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW UEN : 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL : 64532121 VINCENT FAX : 64599795 ACC/64590433
ATTN : 4532121

TAX INVOICE : AR202501-09459
DATE : 02/01/2025
CUSTOMER ID : VIN002
VEH REG. NO. : SNL4789C
TERMS : 30 DAYS
PO NO. :

PAGE NO. : Page 2 of 8
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
15.	52112-V1901 ZWR90-NOAH	FRT BUMPER RH	CC CC12-H-09B	1	250.00	250.00
16.	T81210-48051 ZSU60 AVU65	FOG LAMP RH	CC CC12-M-01C	1	240.00	240.00
17.	T81220-48051 ZSU60 AVU65	FOG LAMP LH	CC CC12-M-01B	1	240.00	240.00
18.	52128-V1121 ZWR90	FRT TOWING COVER	CC CC12-G-3B5	1	30.00	30.00
19.	52115-V1010 ZWR90-NOAH	FRT BUMPER S/RETAINER RH	CC CC12-G-03B1	1	70.00	70.00
20.	52116-V1010 ZWR90-NOAH	FRT BUMPER S/RETAINER LH	CC CC12-H-02A5	1	70.00	70.00
21.	52611-V1010 ZWR90	FRT BUMPER SPONGE	CC CC12-O-07D	1	70.00	70.00
22.	52021-V1010 ZWR90	FRT BUMPER REINFORCEMENT	CC CC12-J-01B	1	290.00	290.00
23.	57013-V1010 ZWR90	BRKT SUB-ASSY, FRT S/MEMBER RH	CC C14-F1-3A4	1	140.00	140.00
24.	57014-V1010 ZWR90	BRKT SUB-ASSY, FRT S/MEMBER LH	CC C14-II-1A2	1	140.00	140.00
25.	52618-V1010 ZWR90	FRT BUMPER LOWER SPONGE	CC CC12-O-07D	1	70.00	70.00
26.	51451-V1010 ZWR90	COVER, ENGINE UNDER, CTR	CC CC12-L-06S	1	150.00	150.00
27.	90467-07220 ZYX10 MXGH12	CLIP, FRT FENDER MLDG	CC CC12-N-03B9	10	2.00	20.00
28.	52719-V1901 ZWR90	COVER, FRT BUMPER CENTER	CC CC12-O-04C1	1	450.00	450.00
29.	89341-50080-C0 AAZH25 MXPL10 AALH15	SENSOR, ULTRASONIC	CC C14-H1-2C5	3	180.00	540.00

CONTINUE NEXT PAGE

[P] 21/01/2025 13:11:09

Goods Sold are not refundable for Cash.



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
60 JALAN LAM HUAT CARIOS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625226 / 62569633 FAX: 63626977



Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0118201-3 CO. REG. NO.: 199307741M

PAYNOW UEN: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL : 64532121 VINCENT FAX : 64599795 ACC/64590433
ATTN : 4532121

TAX INVOICE : AR202501-09459
DATE : 02/01/2025
CUSTOMER ID : VIN002
VEH REG. NO. : SNL4789C
TERMS : 30 DAYS
PO NO. :

PAGE NO. : Page 3 of 8
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
30.	T82112-V1010 ZWR90	FRT SENSOR WIRE	CC NEW	1	150.00	150.00
31.	53205-V1010 ZWR90	SUPPORT TOP PANEL	CC C13-I1-6B	1	280.00	280.00
32.	53210-V1010 ZWR90-NOAH	SUPPORT PANEL RH	CC CC12-G-08A1	1	270.00	270.00
33.	53220-V1010 ZWR90-NOAH	SUPPORT PANEL LH	CC C13-L1-3B	1	270.00	270.00
34.	53028-V1010 ZWR90	SUPPORT, RADIATOR, LOWER	CC C13-I1-6B	1	260.00	260.00
35.	53209-V1010 ZWR90	BRACE PANEL	CC CC12-I-01B3	1	80.00	80.00
36.	884A0-33030 AXVH70 ZWR90	A/C CONDENSER	CC CC12-J-06B	1	800.00	800.00
37.	88711-V1020 ZWR90	HOSE, COOLER REFRIGERANT DISCHARGER	CC CC12-O-3A1	1	280.00	280.00
38.	16400-37430 ZWR90	RADIATOR	CC C14-K1-1B	1	920.00	920.00
39.	16572-V1020 ZWR90	HOSE, RADIATOR, NO.2	CC CC12-H-01A1	1	40.00	40.00
40.	16571-V1020 ZWR90	HOSE, RADIATOR, NO.1	CC CC12-H-01A3	1	40.00	40.00
41.	16593-V1010 ZWR90-NOAH	GUIDE, RAD AIR, NO.1 RH	CC CC12-G-02A1	1	80.00	80.00
42.	16595-V1010 ZWR90-NOAH	GUIDE, RAD AIR, NO.1 LH	CC CC12-G-01A3	1	80.00	80.00
43.	16360-37190 ZWR90 AXVH30	FAN ASSY, W/MOTOR	CC CC12-J-06B	1	750.00	750.00

CONTINUE NEXT PAGE

[P] 21/01/2025 13:11:09

Goods Sold are not refundable for Cash.



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
60 JALAN LAM HUNT CARROS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625226 / 62569633 FAX: 63626977



Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW UEN: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL: 64532121 VINCENT FAX: 64599795 ACC/64590433
ATTN: 4532121

TAX INVOICE : AR202501-09459
DATE : 02/01/2025
CUSTOMER ID : VIN002
VEH REG. NO. : SNL4789C
TERMS : 30 DAYS
PO NO. :

PAGE NO. : Page 4 of 8
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
44.	16523-38010 ZWR90	CUSHION, RADIATOR SUPPORT	CC CC12-N-02B3	1	20.00	20.00
45.	16470-V1010 ZWR90	SPARE TANK	CC CC12-O-10A2	1	130.00	130.00
46.	85315-V1010 ZWR90	WIPER TANK	CC CC12-O-10A2	1	100.00	100.00
47.	85301-V1010 ZWR90	WIPER TANK NECK	CC CC12-H-01A3	1	60.00	60.00
48.	86520-20300 ZGE20 AXVH80 ZWR80/90	HORN, LOW PITCH	CC CC12-O-07B7	1	60.00	60.00
49.	86570-V1010 ZWR90	SPEAKER ASSY, VEHICLE APPROACHING	CC NEW	1	130.00	130.00
50.	17893-V1010 ZWR90	RESONATOR, INTAKE AIR	CC CC12-Q1-SIDE	1	120.00	120.00
51.	17971-V1010 ZWR90	INLET, COOL AIR, NO.1	CC C14-G1-3A2	1	130.00	130.00
52.	17752-V1010 ZWR90	INLET, AIR CLEANER, NO.2	CC C14-I1-2D6	1	60.00	60.00
53.	17700-37410 ZWR90 ZVW60	AIR CLEANER	CC CC12-K-01E	1	450.00	450.00
54.	17880-V1010 ZWR90	HOSE ASSY, AIR CLEANER	CC NEW	1	60.00	60.00
55.	17850-V1010 ZWR90	BRKT, AIR CLEANER SUPPORT	CC CC12-H-2B10	1	50.00	50.00
56.	17120-37110 ZVW50 ZVW60 ZYX10 ZWR90	INTAKE MANIFOLD	CC CC12-J-03E	1	350.00	350.00
57.	188370-28030 ZWR90	A/C COMPRESSOR ASSY	CC C13-I1-1B	1	2800.00	2,800.00
58.	82741-V1020 ZWR90	BLOCK, ENGINE ROOM RELAY	CC NEW	1	140.00	140.00

CONTINUE NEXT PAGE

[P] 21/01/2025 13:11:09

Goods Sold are not refundable for Cash.



日美汽車私人有限公司 JAE AUTO PTE LTD

BLK 3018 UBI TRAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
60 JALAN LAM HOUT CARIOS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625200 / 63669633 FAX: 63626977



Email: jaeauto@pacific.net.sg
GST REG. NO.: R12-0119201-3 CO. REG. NO.: 199307741M

PAYNOW UEN: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9795

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL: 64532121 VINCENT FAX: 64599795 ACC/64590433
ATTN: 4532121

TAX INVOICE : AR202501-09459
DATE : 02/01/2025
CUSTOMER ID : VIN002
VEH REG. NO. : SNL4789C
TERMS : 30 DAYS
PO NO. :

PAGE NO. : Page 5 of 8
CURR. : SGD

SQ	STOCKID	DESCRIPTION	SKL	QTY	U/PRICE	AMOUNT
59.	82663-V1020 ZWR90	COVER, RELAY BLOCK, LOWER	CC NEW	1	130.00	130.00
60.	T74404-V1020 ZWR90	CARRIER SUB-ASSY, BATTERY	CC NEW	1	140.00	140.00
61.	12305-V1030 ZWR90	ENG MTG RH	CC CC12-N-01A3	1	420.00	420.00
62.	53811-V1010 ZWR90-NO. H	FRT FENDER RH	CC C14-I-06A	1	400.00	400.00
63.	53812-V1010 ZWR90-NO. H	FRT FENDER LH	CC CC12-N-08D	1	400.00	400.00
64.	53805-V1020 ZWR90-VO. Y	FRT FENDER LINER RH	CC CC12-D-11S	1	170.00	170.00
65.	53806-V1020 ZWR90-VO. Y	FRT FENDER LINER LH	CC C14-L1-6A	1	170.00	170.00
66.	90467-07166 A1J.	CLIP, FOR FENDER LINER	CC CC12-N-03B7	20	2.00	40.00
67.	53827-V1010 ZWR90	PROT, FRT FENDER SIDE, RH	CC CC12-H-5A3	1	110.00	110.00
68.	56101-V1907 ZWR90 NO. A. 2	FRT W/SCREEN GLASS (ADAS) SXV20	CC CC6-E-4H	1	900.00	900.00
69.	75553-V1010 ZWR90 NO. A. 2	FRT W/S SIDE MLD RH	CC CC6-A-1I	1	90.00	90.00
70.	55708-V1010 ZWR90	WIPER GARNISH	CC C13-L1-4B	1	380.00	380.00
71.	53823-V1010 ZWR90	WIPER GARNISH S/COVER RH	CC CC12-G-01B2	1	40.00	40.00
72.	53824-V1010 ZWR90	WIPER GARNISH S/COVER LH	CC CC12-G-4B6	1	40.00	40.00
73.	55302-V1010-01 ZWR90	PANEL, SUB-ASSY, INSTRUMENT, UPPER	CC CC12-I-08B	1	900.00	900.00

CONTINUE NEXT PAGE

[P] 21/01/2025 13:11

Goods Sold are not returnable for Cash.



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 L1 ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453123 FAX: 67454442, 67450616 (Account)

WAREHOUSE 4
60 JALAN LAMBUAT CARLOS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625616 / 62569633 FAX: 63626977



Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW 4: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOMOTIVE
SECTOR B
SINGAPORE 575122
TEL: 64532121 VINCEN FAX: 64599795 ACC/64590433
ATTN: 4532121

TAX INVOICE : AR202501-09459
DATE : 02/01/2025
CUSTOMER ID : VIN002
VEH REG. NO. : SNL4789C
TERMS : 30 DAYS
PO NO. :

PAGE NO. : Page 6 of 8
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
74.	45130-28630 ZWR90	AIR BAG RH	CC CC14-D-06B	1	1800.00	1,800.00
75.	73960-V1010 ZWR90	AIR BAG LH	CC C13-II-5D	1	2200.00	2,200.00
76.	62170-V1010 ZWR90	ROOF AIR BAG RH	CC NEW	1	2100.00	2,100.00
77.	62180-V1010 ZWR90	ROOF AIR BAG LH	CC NEW	1	2100.00	2,100.00
78.	T63310-2879 ZWR90	ROOF LINING	CC NEW	1	2800.00	2,800.00
79.	73210-28861 ZWR90	FRT SEAT BELT RH	CC CC12-N-03C	1	800.00	800.00
80.	73220-28831 ZWR90	FRT SEAT BELT LH	CC CC12-N-05C	1	800.00	800.00
81.	89170-28480 ZWR90	COMPUTER, AIR BAG	CC NEW	1	1700.00	1,700.00
82.	89173-59415 MXPL10 ZWR90	SENSOR, AIR BAG, FRT L/R	CC CC12-G-03B5	1	340.00	340.00
83.	52030-V1010 ZWR90	FRT BUMPER COVER RH	CC CC12-N-08B	1	280.00	280.00
84.	52040-V1010 ZWR90	FRT BUMPER COVER LH	CC CC12-N-07B	1	280.00	280.00
85.	16592-V1010 ZWR90	GUIDE, RAD AIR, NO.3	CC CC12-G-02A3	1	80.00	80.00
86.	51410-V1010 ZWR90	COVER, ENG UNDER, NO.1	CC CC12-K-09E	1	280.00	280.00
87.	161A0-39045 ZVW60 ZWR90	WATER PUMP	CC CC12-L-03B	1	270.00	270.00
88.	82662-V1020 ZWR90	COVER, RELAY BLOCK, UPPER, NO.3	CC NEW	1	80.00	80.00

CONTINUE NEXT PAGE

[P] 21/01/2025 13:13

Goods Sold are not refundable for Cash.



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 BI ROAD 1 #01-121 SINGAPORE 408710
TEL: 6745 3333 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
60 JALAN HUAT CAIRO CENTRE #B1-05/06 SINGAPORE 737869
TEL: 6362 26 / 62569633 FAX: 63626977



Email: jae@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW N: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9795

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTO CITY
SECTOR B
SINGAPORE 57122
TEL: 64532121 V CENT FAX: 64599795 ACC/64590433
ATTN: 4532121

TAX INVOICE : AR202501-09459
DATE : 02/01/2025
CUSTOMER ID : VIN002
VEH REG. NO. : SNL4789C
TERMS : 30 DAYS
PO NO. :

PAGE NO. : Page 7 of 8
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
89.	82662-V1040 ZWR90	COVER, RELAY BLOCK, UPPER, NO.1	CC NEW	1	90.00	90.00
90.	51444-V1010 ZWR90	COVER, ENG UNDER, RIGHT	CC CC12-M-07S	1	70.00	70.00
91.	G9226-V1010 ZWR90	HOSE, INVERTER COOLING, NO.2	CC NEW	1	150.00	150.00
92.	G9225-V1010 ZWR90	HOSE, INVERTER COOLING, NO.1	CC NEW	1	60.00	60.00
93.	G910G-76030 ZWR90	TANK, INVERTER RESERVE W/O CAP	CC NEW	1	160.00	160.00
94.	G9229-V1010 ZWR90	HOSE, INVERTER COOLING, NO.5	CC NEW	1	60.00	60.00
95.	75533-28070 ZWR90 NO. H"22	FRT W/S MLD	CC CC6-BC-4FA	1	40.00	40.00
96.	1821H2-V1010 ZWR90	HV AIR CONDITIONER WIRE	CC NEW	1	480.00	480.00
97.	88712-V1020 ZWR90	HOSE, COOLER REFRIGERANT SUCTION	CC CC12-O-03A2	1	250.00	250.00
98.	88710-V1030 ZWR90	TUBE & ACCESSORY, AIR COND	CC NEW	1	390.00	390.00
99.	22030-37060 ZWR90 ZV 40 ZVW50 ZVW60	THROTTLE BODY	CC CC12-K-04B	1	920.00	920.00
100.	16561-V1010 ZWR90-NO. H	SEAL, RAD TO SUPPORT, NO.1	CC CC12-O-04C2	1	100.00	100.00
101.	17341-V1010 ZWR90	LOW RESONATOR	CC CC12-G-03B2	1	140.00	140.00

CONTINUE NEXT PAGE

[P] 21/01/2025 13:11 9

Goods Sold are not refundable for Cash



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 ROAD 1 #01-121 SINGAPORE 408710
TEL: 6745 FAX: 67454442, 67450616 (Account)

WAREHOUSE UNIT CARRIOS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 6362 FAX: 62569633 FAX: 63626977



Email: jae@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M
PAYNOW NO.: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9839



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOMOTIVE
SECTOR B
SINGAPORE 573922
TEL : 64532121 V. CENT FAX : 64599795 ACC/64590433
ATTN : 4532121

TAX INVOICE : AR202501-09459
DATE : 02/01/2025
CUSTOMER ID : VIN002
VEH REG. NO. : SNL4789C
TERMS : 30 DAYS
PO NO. :

PAGE NO. : Page 8 of 8
CURR. : SGD

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
------------	-------------	---------	-----	---------	--------

SUB-TOTAL : 40,940.00
ADD GST 9.00 % 3,684.60

U & O.E TOTAL AMOUNT SGD : 44,624.60

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : AO



This is computer generated document.
No signature is required.

ORIGINAL

Signature / Co Stamp / Date

[P] 21/01/2025 13:09
Goods Sold are non refundable for Cash.
Interest Rate of 1.5 per month will be imposed on OverDue Account(s).