

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/FC/24/10197/4_{v3}**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 2680xat Workshop m/s Trans Eureka's 10an.

of _____

Insured: SAC3801A

Policy No. _____

Claims No. D24009903MFCT

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 852K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 042d

Date: _____ Vehicle: IN / OUT

Person Contacted: 17A53228Veh No: SLU 2680x Yr Regn: 28/11/17Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: no2de 6 c.c. 2488Colour: blue A/C: Insured / Std / NI / NASp. Reading: 1223-82 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Jm66L1031J0131604Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/45 R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 9/11/24 D.O.I. 22/11/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction dep 14k.4/12/24 P/P & 3565-05 inform N/R way (red 3048.36, 46%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 042D

Vehicle Details

Vehicle No.: SLU2680X
Vehicle to be Exported: No
Intended Deregistration Date: 22 Nov 2024
Vehicle Make: MAZDA
Vehicle Model: MAZDA6 SEDAN 2.5 AT PREMIUM EU6
Primary Colour: Blue
Manufacturing Year: 2017
Engine No.: PY21026707
Chassis No.: JM6GL1031J0131604
Maximum Power Output: 141.0 kW (189 bhp)
Open Market Value: \$25,220.00
Original Registration Date: 28 Nov 2017
First Registration Date: 28 Nov 2017
Transfer Count: 0
Actual ARF Paid: \$27,308.00 13654

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Nov 2027
PARF Rebate Amount: \$17,750.00

Intended COE Rebate Details

COE Expiry Date: 27 Nov 2027
COE Category: E - Open - all except motorcycle
COE Period(Years): 10
QP Paid: \$48,005.00
COE Rebate Amount: \$14,468.00
Total Rebate Amount: \$32,218.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 22 Nov 2024

OK



Mazda 6 2.0A

\$46,888

Instl. \$1,240 /mth

\$14,250 /yr

28-Apr-2017

(2yrs 5mths COE left)

94,000 km

1,998 cc

1 Owner



1 year warranty cover on engine and gearbox, free servicing worth \$400, drive with assurance with 5 stars reviews! Very well maintained, welcome STA evaluation, regular serviced by previous owner. Bank/in house loan/balloon scheme available with low interest rate. Please call or WhatsApp our friendly sales consultant for appointment or viewing.

Warranty

SG Car Choice Pte Ltd|Posted 04-Nov-2024

☐ Compare

Handy Tools

View All

Loan Calculator



Used Car Depre Finder



Bidded Carplate




COE Renewal



Petrol Discount



My Shortlist



Mazda 6 2.0A

Executive

\$52,800

Instl. \$1,163 /mth

\$13,960 /yr

31-Oct-2017

(2yrs 11mths COE left)

107,484 km

1,998 cc

1 Owner



Executive Model! 1 Owner. Full service history with Eurokars. Perfect for the whole family with comfortable legroom space and ample boot space. Fuel efficient, achieving up to 15 km/l with its SKYACTIVE technology. View Today!

BuySafe

Trillium Automobile Pte Ltd|Posted 26-Oct-2024

☐ Compare

PREMIUM AD



Mazda 6 2.0A

Executive

\$55,800

Instl. \$1,230 /mth

\$15,000 /yr

30-Oct-2017

(2yrs 11mths COE left)

68,000 km

1,998 cc

2 Owners



Accident free. Non phv. Well maintained. Perfect for the whole family with comfortable legroom space and ample boot space. Fuel efficient, achieving up to 15 km/l with its skyactive technology. Comfortable and quiet drive assured. Call/WhatsApp's for viewing appointment/more details

Posted 03-Oct-2024

☐ Compare

DIRECT OWNER



Mazda 6 2.5A Sunroof

\$48,800

Instl. \$1,209 /mth

\$13,250 /yr

30-Jun-2017

(2yrs 7mths COE left)

N.A

2,488 cc

2 Owners



Stylish, spacious luxury sedan. Fuel efficient with the SkyActiv-G engine had every feature of a luxury sedan, sunroof, dual electric leather seat, memory seats and Bose sound system. Auto rain sensors and auto headlights. High loan approval with flexible in house financing/bank loan available, trade in most welcome. So hurry come and view, test drive now!

Posted 19-Sep-2024

☐ Compare



QUOTATION

P/P # 3565-05

No of Authorised
man means 3 days
22/11/24
Take photo before repair

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN:MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 2.5L PREMIUM BLACK LS
CHASSIS NO.: JM6GL1031J0131604
ENGINE NO.: PY21026707
REG NO.: SLU2680X
REGN DATE: 28/11/2017

PAGE NO.: 1
DOCUMENT NO.: 1595
DOCUMENT DATE: 18/11/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 22813
REF. NO.:
DATE IN:
EXT. WTY: 27/11/2022
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	MS FIRST TP CLAIM				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA.			792	1,584.00	S
SUB	TO RESPRAY REAR BUMPER.			756	1,512.00	S
SUB	TO TRANSFER REVERSE SENSORS.			180	330.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			120	250.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			180	300.00	S
SUB	SUNDRIES.			20	50.00	S
GJY1-50-221	REAR BUMPER GJ/GL	1.00	1,260.75	*NO STOCK	1,260.75	S
BHN1-50-0Z1A	GROMMET,SCREW	4.00	2.36	*NO STOCK	9.44	S
B45A-56-146A	FASTENER	6.00	2.36	STOCK	14.16	S
G4YL-50-EL1 13	COVER(L),TOWING HOOK	1.00	43.80	*NO STOCK	43.80	S
G4YL-50-EK1 13	COVER(R),TOWING HOOK	1.00	43.80	STOCK	43.80	S
DFR5-50-251	BRACKET,BUMPER SKYACTIV	1.00	4.64	*NO STOCK	4.64	S
GHK1-50-260	REINF.,REAR BUMPER GJ/GL	1.00	523.08	*NO STOCK	523.08	S
KD45-67-UC5A1	RETAINER RR SENSOR	2.00	15.77	*NO STOCK	31.54	S
GMK6-67-UC1	1SENSOR,ULTRASONIC KE/BN	2.00	184.59	*NO STOCK	369.18	S
GS1D-50-EM1A	TAPE,PROTECTOR	4.00	7.42	*NO STOCK	29.68	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN. 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402
23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 2.5L PREMIUM BLACK LS
CHASSIS NO.: JM6GL1031J0131604
ENGINE NO.: PY21026707
REG NO.: SLU2680X
REGN DATE: 28/11/2017

PAGE NO.: 2
DOCUMENT NO.: 1595
DOCUMENT DATE: 18/11/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 22813
REF. NO.:
DATE IN:
EXT. WTY: 27/11/2022
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
GMC8-67-290	CORD, SHORT GL	1.00	178.10	*NO STOCK	178.10	S
GJA1-51-153	GASKET(R), RR.COMB.GJ/GL	1.00	39.62	STOCK	39.62	S
GJA1-51-163	GASKET(L), RR.COMB.GJ/GL	1.00	39.62	STOCK	39.62	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	2,587.41	O	-	-			
Surcharge	0.00	S	9.00%	6,613.41	595.21	7,208.62	
Labour	4,026.00						
Menus	0.00						
Gross					6,613.41	595.21	7,208.62
Less: Deposit**					0.00	0.00	0.00
Amount Due					6,613.41	595.21	7,208.62

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 2.5L PREMIUM BLACK LS
CHASSIS NO.: JM6GL1031J0131604
ENGINE NO.: PY21026707
REG NO.: SLU2680X
REGN DATE: 28/11/2017

PAGE NO.: 1
DOCUMENT NO.: 1628
DOCUMENT DATE: 03/12/2024
POS ID: MU
PRINTED BY: Wong Chun Wei
SERVICE ADV: Wong Chun Wei
CSP/OP CODE: 1
DEPT: 22813
WIP NO.:
REF. NO.:
DATE IN: 27/11/2022
EXT. WTY: 0
MILEAGE:

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	MS FIRST TP CLAIM				0.00	O
SUB	MZ 6 UBI				792.00	S
	TO REMOVE & REPLACE REAR BUMPER.					
	AND ALL ACCIDENT AFFECTED AREA.					
	- PO24223					
SUB	MZ 6 UBI				756.00	S
	TO RESPRAY REAR BUMPER.					
	- PO24223					
SUB	MZ 6 UBI				180.00	S
	TO TRANSFER REVERSE SENSORS.					
	- PO24223					
SUB	MZ 6 UBI				120.00	S
	TO CHECK ELECTRICAL SYSTEM					
	FOR PROPER FUNCTIONING.					
	- PO24223					
SUB	MZ 6 BUI				180.00	S
	TO REPROGRAMME AFTER THE					
	ACCIDENT REPAIR WORKS.					
	- PO24223					

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



TRANSEUROKARS
Eurokars Group

Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402
23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 2.5L PREMIUM BLACK LS
CHASSIS NO.: JM6GL1031J0131604
ENGINE NO.: PY21026707
REG NO.: SLU2680X
REGN DATE: 28/11/2017

PAGE NO.: 2
DOCUMENT NO.: 1628
DOCUMENT DATE: 03/12/2024
POS ID: MU
PRINTED BY: Wong Chun Wei
SERVICE ADV: Wong Chun Wei
CSP/OP CODE: 1
DEPT: 22813
WIP NO.: 27/11/2022
REF. NO.: 0
DATE IN: 0
EXT. WTY: 0
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
SUB	MZ 6 UBI SUNDRIES. - PO24223				20.00	S
GJY1-50-221	REAR BUMPER GJ/GL	1.00	1,260.75	*ISSUED	1,260.75	S
BHN1-50-0Z1A	GROMMET,SCREW	4.00	2.36	*ISSUED	9.44	S
B45A-56-146A	FASTENER	6.00	2.36	*ISSUED	14.16	S
G4YL-50-EL1 13	COVER(L),TOWING HOOK	1.00	43.80	*ISSUED	43.80	S
G4YL-50-EK1 13	COVER(R),TOWING HOOK	1.00	43.80	*ISSUED	43.80	S
DFR5-50-251	BRACKET,BUMPER SKYACTIV	1.00	4.64	*ISSUED	4.64	S
KD45-67-UC5A1	RETAINER RR SENSOR	2.00	15.77	*ISSUED	31.54	S
GS1D-50-EM1A	TAPE,PROTECTOR	4.00	7.42	*ISSUED	29.68	S
GJA1-51-153	GASKET(R),RR.COMB.GJ/GL	1.00	39.62	*ISSUED	39.62	S
GJA1-51-163	GASKET(L),RR.COMB.GJ/GL	1.00	39.62	*ISSUED	39.62	S

	GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	O	-		-	3,565.05	320.85	3,885.90
Surcharge	S	9.00%	3,565.05	320.85	0.00	0.00	0.00
Labour					3,565.05	320.85	3,885.90
Menus							

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



TRANSEUROKARS
Eurokars Group

Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417