



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept				S1000006 / ICIII1		Mdm Ivy Lam Bee Lian (Lan Meilian) 14A Lorong 7 Toa Payoh #25-233 Singapore 311014 Mobile: 97304413			
				Document No. 0					
				Document Date 14/12/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2024	ZRE210R	GEXGPZ S3	20/08/2024	SNS5526B	0	34604	72/DS/SNS5526B		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MR2BE3BE800030232		1ZR3A89375	60	Thomas Pang W T	11/12/2024	8.00	14/12/2024	18.00	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI TP INS:INDIA INTERNATIONAL INSURANCE TP VEH:SGT8571C DATE OF ACC:08.11.2024 BY:LKK-TAUFIKH @ 11.12.2024 03 WORKING DAYS							50.00
2	B	BP-LAB2	DRILL HOLE AND INSTALL REVERSE SENSOR		BP29				198.00
3	B	BP-LAB2	CHECK WIRING SYSTEM		BP29				134.64
4	B	BP-ECU2	TO RESET ECU AND REPROGRAMME		BP63				198.00
5	B	BP-MECH2	TO CONDUCT ADJUSTMENT ON BLIND SPOT SENS OR		BP63				198.00
6	B	BP-LAB2	REPLACE ACC DAMAGED PARTS		BP29				792.00
7	B	BP-RES2	REPLACE ACC DAMAGED PARTS		BP20				656.00
8	S	PSP PER PANE	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION		0619				91.59
9	1	S52159-0Z961	COVER, RR BUMPER L/C			1.00	824.30		824.30
10	2	S52462-02340	PAD, RR BUMPER, RH			2.00	28.00		56.00
11	3	S52161-0K040	PIECE, RR BUMPER			10.00	5.80		58.00
12	4	S81920-02360	REFLECTOR ASSY, REFL			1.00	54.10		54.10
13	5	SPC507-12005 2A	BACK SENSOR (1K3, CELESTITE GR			1.00	224.10		224.10
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 3,534.73		
 <									

Company Copy