

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One S(038987)

Attention : Motor Claim Department
Contact : 63374779 Fax No. : 63389267

not Authorised
skh
motor
12/11/24

2/5 & 16,700
cheapest Alternative
15 days

Estimate : ES709702

Date : 12/11/2024
Vehicle Num. : SLH309B
Make/Model : TOYOTA WISH
Chassis/Eng# : JTDGG20W80J005869
Accident Date : 12/11/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1PC	TAILGATE <i>Body ID</i>		2,263.80 ✓
2.	1PC	TAILGATE GLASS <i>shattered</i>		1,480.50 ✓
3.	1PC	TAILGATE GLASS MOULDING <i>new</i>		149.90 ✓
4.	1PC	REAR WIPER LINKAGE <i>motor sent to sm</i>	801.20	1,035.30 ✓
5.	1PC	REAR WIPER ARM <i>new</i>		110.60 X
6.	1PC	REAR WIPER BLADE <i>new</i>		59.70 X
7.	1PC	REAR WIPER SMALL COVER <i>new</i>		23.30 X
8.	1PC	TAILGATE TOP SPOILER <i>new</i>		981.30 X
9.	1PC	TAILGATE LOGO EMBLEM <i>new</i>		73.50 ✓
10.	1PC	TAILGATE EMBLEM - ELEGANCE <i>new</i>		63.20 ✓
11.	1PC	TAILGATE EMBLEM - VALVEMATIC <i>new</i>		66.90 ✓
12.	1PC	TAILGATE CHROME MOULDING <i>new</i>		401.90 ✓
13.	2PC	TAILGATE LAMP <i>new</i>	452.40	904.80 ✓
14.	2PC	TAILGATE LAMP SPONGE <i>new</i>	45.00	90.00 X
15.	1PC	TAILGATE INNER TRIM BOARD <i>new / trim</i>		503.50 ✓
16.	1PC	TAILGATE LOCK <i>new / sm</i>		571.50 ✓
17.	1PC	TAILGATE WEATHERSTRIP <i>new</i>		465.50 ✓
18.	2PC	TAILLAMP <i>new</i>	545.90	1,091.80 ✓
19.	2PC	TAILLAMP SPONGE <i>new</i>	45.00	90.00 X
20.	1PC	N/S REAR FENDER <i>body ID / new</i>		1,652.70 ✓
21.	1PC	N/S REAR FENDER GLASS <i>new</i>		568.40 X
22.	1PC	FRONT BUMPER <i>new</i>	761.20	911.60 ✓

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One S(038987)

Attention : Motor Claim Department

Contact : 63374779 Fax No. : 63389267

Estimate : ES709702

Date : 12/11/2024
Vehicle Num. : SLH309B
Make/Model : TOYOTA WISH
Chassis/Eng# : JTDGG20W80J005869
Accident Date : 12/11/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	2PC	FRONT BUMPER SIDE RETAINER 11	96.50	193.00 X
24.	1PC	FRONT BUMPER SPONGE 10.1		141.20 /
25.	1PC	FRONT BUMPER REINFORCEMENT 22		470.40 /
26.	1PC	FRONT BUMPER REINFORCEMENT BRACKET 11		70.30 X
27.	1PC	RADIATOR GRILLE 11		580.90 /
28.	2PC	HEADLAMP holder one	1,951.00	3,902.00 /
29.	2PC	HEADLAMP LOWER BRACKET NS	79.80	159.60 X
30.	2PC	FOG LAMP 11	473.20	946.40 X
31.	2PC	FOG LAMP CHROME 11	118.50	237.00 X
32.	2PC	FOG LAMP GARNISH - SMALL 7m1	79.80	159.60 /
33.	1PC	FRONT SUPPORT PANEL 3m1	1,655.20	2,058.80 /
34.	1PC	BRACE PANEL 3m1		129.20 /
35.	2PC	RADIATOR AIR GUIDE 26 1/2" x 11"	89.50	179.00 /
36.	1PC	AIR CON CONDENSER 18 1/2" x 10"		2,494.50 /
37.	1PC	AIR-CON SUCTION PIPE 11		636.40 X
38.	1PC	AIR-CON DISCHARGE PIPE 11		674.50 X
39.	1PC	RADIATOR 26 1/2" x 11"	2,422.10	2,979.00 /
40.	1PC	RADIATOR FAN COWLING 11		366.90 /
41.	1PC	RADIATOR FAN BLADE 11		391.70 X
42.	1PC	RADIATOR FAN MOTOR 11		919.70 X
43.	1PC	RADIATOR SPARE TANK 11		263.50 X
44.	1PC	WIPER WASHER TANK 11		96.80 X
45.	1PC	N/S REAR FENDER INNER SHIELD 11	755.10	145.20 X
46.	1PC	REAR BUMPER 21.5		911.60 /

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One S(038987)

Attention : Motor Claim Department
Contact : 63374779 Fax No. : 63389267

Estimate : ES709702

Date : 12/11/2024
Vehicle Num. : SLH309B
Make/Model : TOYOTA WISH
Chassis/Eng# : JTDGG20W80J005869
Accident Date : 12/11/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
47.	2PC	REAR BUMPER SIDE RETAINER - LONG <i>n/s Bent</i>	149.10	298.20 <i>1/2 C</i>
48.	1 PC	O/S REAR FENDER INNER SHIELD <i>11</i>		145.20 <i>X</i>
49.	1 SET	REVERSE SENSOR <i>malfunction</i>		250.00 <i>✓</i>
50.	2PC	REAR BUMPER SIDE RETAINER - SHORT <i>n/s Bent</i>	70.20	140.40 <i>1/2 C</i>
51.	2PC	REAR BUMPER REFLECTOR <i>11</i>	83.40	166.80 <i>X</i>
52.	1PC	REAR END PANEL <i>body 22</i>		871.40 <i>✓</i>
53.	1PC	REAR END PANEL GARNISH <i>7ml</i>	366.50	413.40 <i>✓</i>
54.	2PC	REAR END PANEL BRACKET <i>SVC</i>	108.80	217.60 <i>X</i>
55.	2PC	REAR FENDER TRIM BOARD <i>Re / Torn</i>	977.90	1,955.80 <i>✓</i>
56.	1PC	REAR COMPARTMENT PANEL <i>R</i>		886.30 <i>X</i>
57.	1PC	REAR COMPARTMENT PANEL BOARD <i>merged</i>	500.00	999.00 <i>✓</i>
58.	2PC	REAR NUMBER PLATE LAMP <i>11</i>	112.40	224.80 <i>X</i>
59.	1PC	N/S TAILLAMP PANEL <i>22 / bent</i>		171.70 <i>✓</i>
60.	1PC	EXHAUST MUFFLER HEATSHIELD <i>11</i>		164.30 <i>X</i>
61.	1PC	EXHAUST MUFFLER RUBBER HANGER <i>11</i>		56.90 <i>X</i>
62.	1PC	BONNET <i>Buc</i>		1,373.20 <i>✓</i>
63.	2PC	BONNET HINGES <i>Bent</i>	81.80	163.60 <i>✓</i>
64.	1PC	BONNET INSULATOR <i>11</i>		570.00 <i>X</i>
65.	1 SET	rear antenna sensor <i>no</i>	228.30	650.00 <i>✓</i>
66.	1PC	BONNET LOGO <i>no</i>		73.50 <i>✓</i>
67.	1PC	BONNET LOCK <i>1m</i>		129.20 <i>✓</i>
List Total S\$:				42,588.20
25.00% Discount S\$:				10,647.05
				31,941.15

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One S(038987)

Attention : Motor Claim Department
Contact : 63374779 Fax No. : 63389267

Estimate : ES709702

Date : 12/11/2024
Vehicle Num. : SLH309B
Make/Model : TOYOTA WISH
Chassis/Eng# : JTDGG20W80J005869
Accident Date : 12/11/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	1PC	TAILGATE SEALANT <i>11</i>		80.00 <i>X</i>
2.	1PC	TAILGATE GLASS SOLAR FILM <i>11</i>		450.00 <i>250</i>
3.	1PC	TAILGATE GLASS SEALANT <i>11</i>		40.00 <i>1</i>
4.	1PC	TAILGATE INNER SEAL <i>11</i>		80.00 <i>20</i>
5.	1SET	TAILGATE TOP SPOILER CLIPS <i>11</i>		50.00 <i>X</i>
6.	10PC	TAILGATE CHROME MOULDING CLIP - FEMALE <i>11</i>	5.00	50.00 <i>X</i>
7.	10PC	TAILGATE CHROME MOULDING CLIP - MALE <i>11</i>	5.00	50.00 <i>X</i>
8.	1SET	TAILGATE INNER TRIM BOARD CLIPS <i>11</i>		50.00 <i>30</i>
9.	1PC	N/S REAR FENDER GLASS SEALANT <i>11</i>		40.00 <i>✓</i>
10.	1PC	N/S REAR FENDER GLASS INNER SEAL <i>11</i>		80.00 <i>X</i>
11.	1SET	FRONT BUMPER CLIP <i>11</i>		50.00 <i>30</i>
12.	2 PC	RADIATOR GRILLE STOPPER CLIP <i>11</i>	25.00	50.00 <i>X</i>
13.	1 PC	N/S REAR FENDER GLASS SOLAR FILM <i>11</i>		350.00 <i>X</i>
14.	1BTL	COOLANT <i>11</i>		40.00 <i>30</i>
15.	1SET	N/S REAR FENDER INNER SHIELD CLIPS <i>11</i>		50.00 <i>X</i>
16.	10 PC	O/S REAR FENDER INNER SHIELD CLIPS <i>11</i>	5.00	50.00 <i>X</i>
17.	1SET	REAR BUMPER CLIP <i>11</i>		50.00 <i>30</i>
18.	1SET	REAR END PANEL GARNISH CLIP <i>11</i>		50.00 <i>X</i>
19.	1SET	REAR FENDER TRIM BOARD CLIPS <i>11</i>		50.00 <i>X</i>
20.	1PC	REAR COMPARTMENT PANEL RUBBER INSULATOR <i>11</i>		400.00 <i>100</i>
21.	1PC	REAR NUMBER PLATE <i>5M4</i>		45.00 <i>40</i>
22.	1 SET	REVERSE CAMERA <i>11</i>		450.00 <i>X</i>

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One S(038987)

Attention : Motor Claim Department
Contact : 63374779 Fax No. : 63389267

Estimate : ES709702

Date : 12/11/2024
Vehicle Num. : SLH309B
Make/Model : TOYOTA WISH
Chassis/Eng# : JTDGG20W80J005869
Accident Date : 12/11/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1SET	BONNET INSULATOR CLIP <i>100</i>		50.00 <i>30</i>
		Special Nett Total S\$:		2,655.00
		LABOUR :		
		TO TRANSFER TAILGATE GLASS		150.00 <i>120</i>
		TO TRANSFER TAILGATE MECHANISMS		150.00 <i>50</i>
		RESPRAY ANTI RUST		150.00 <i>100</i>
		APPLY BODY SEALANT TO CAR JOINTS		150.00 <i>X</i>
		TO CHECK LIGHT AND WIRING	<i>1^</i>	50.00 <i>30</i>
		TO VACCUM,REOIL AND REGAS AIR CON		150.00 <i>100</i>
		INSTALL REVERSE SENSOR		100.00 <i>30</i>
		INSTALL REVERSE CAMERA		150.00 <i>30</i>
		TO REMOVE/REPLACE N/S REAR FENDER GLASS		100.00 <i>✓</i>
		TO REMOVE INNER TRIM,GARNISH AND ETC TO FACILIATE		
		REPAIRS AND TO FIX BACK		150.00 <i>60</i>
		PANEL BEATING -FRONT		900.00 <i>600</i>
		PANEL BEATING - REAR		1,600.00 <i>1200</i>
		TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS		2,800.00 <i>2000</i>
		Labour Total S\$:		6,600.00
E. & O.E.			Total S\$:	41,196.15 =====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One S(038987)

Attention : Motor Claim Department
Contact : 63374779 Fax No. : 63389267

Supplementary Estimate : ES709707

Date : 12/11/2024
Vehicle Num. : SLH309B
Make/Model : TOYOTA WISH
Chassis/Eng# : JTDGG20W80J005869
Accident Date : 11/11/2024
Claim No. :
Reference : SUPP
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	N/S REAR FENDER AIR DUCT		128.80 X
2.	1 PC	AIR-CON FAN MOTOR		919.70 X
3.	1 PC	AIR-CON FAN BLADE		391.70 X
4.	1 PC	FRONT SUPPORT PANEL TOP GARNISH		187.50 ✓
5.	1 PC	BOOT LID ANTENNA		288.10 X
6.	1 PC	REAR WIRE HARNESS		788.40 X
List TotalS\$:				2,704.20
25.00% Discount S\$:				676.05
				2,028.15

E. & O.E.	Total S\$:	2,028.15
		=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH