

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |  |                 |                        |  |
|--|--|--|-----------------|------------------------|--|
| MS   | MS FIRST CAPITAL                           | INSURANCE LTD  | Ref:            | CS3/FCI24110231/Enp3m4 |  |
|  | 16 RAFFLES QUAY                            | IC PUII DINC   | Date:           | 20/11/2024             |  |
|  | #42-01 HONG LEON<br>SINGAPORE 04858        |  | Code:           | FCI2                   |  |
| 1.   | 1. Policy Particulars :- PRE-REPAIR SURVEY |  |                 |                        |  |
|  | Insured Veh.                               | SHB 2261U  | Veh. Inspected  | GBK 3992K              |  |
|  | Policy No.                                 | D-24101860MFCT   | Coverage        | 0                      |  |
|  | Claim No.                                  | D24007798MFCT  | Excess          | \$0.00                 |  |
|  | Assign From                                | HARMINDER  | Assign Date     | 12/11/2024             |  |
| 2. Vehicle Details   |  |  |                 |                        |  |
|  | Make & Model                               | TOYOTA HIACE   | C.C             | 2982                   |  |
|  | Engine No.                                 | 1KDB035099   | Year of Reg.    | 16/07/2020             |  |
|  | Chassis No.                                | JTFHT02P300250506  | Colour          | WHITE                  |  |
|  | Odometer                                   | 132493 KM  | Steering        | IN ORDER               |  |
|  | Brakes                                     | IN ORDER   | General         | FAIR                   |  |
|  | Modification(s)                            | RIMS: STANDARD ALLOY RIM   |                 |                        |  |
| 3. Conditions of Tyres   |  |  |                 |                        |  |
|  |  | Size   | Make            | Balance (mm)           |  |
|  | R/H Front Tyre                             | 195R15   | GETWIN          | 5                      |  |
|  | L/H Front Tyre                             | 195R15   | GETWIN          | 5                      |  |
|  | R/H Rear Tyre                              | 195R15   | GETWIN          | 5                      |  |
|  | L/H Rear Tyre                              | 195R15   | GETWIN          | 5                      |  |
| 4.   | 4. Description of Damages                  |  |                 |                        |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  |  |  |                 |                        |  |
| 5.   | General Information                        |  |                 |                        |  |
|  | Accident Date                              | 03/09/2024   | Inspection Date | 18/11/2024 (11:01)     |  |
|  | Survey held at                             | MHL AUTOMOBILE SERVICES<br>BLK 3006, UBI ROAD 1<br>#01-360<br>SINGAPORE 408700 |                 |                        |  |
| 5a. Remarks  |  |  |                 |                        |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$78,000.00 (EST) E)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000  5b. Estimate Days of Repair |  |  |                 |                        |  |
|  | IMATED NORMAL PI                           | ERIOD FOR REPAIR: 3 Working Days   | •               |                        |  |
| i  |  |  |                 |                        |  |

## CTY

## **CHEN TSUE YEE**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.