

Your Ref : CLMOMVC000004527

Date: 09th December 2024

Our Ref : CS/GAI24110237/Enp3m4

M/s Great American Insurance Company

3 Temasek Avenue

#16-01 Centennial Tower

Singapore 039190

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBD 1953Z
INSURED VEHICLE: GBJ 1387B
ACCIDENT ON 07/08/2024**

Instruction was received to inspect the vehicle Reg. No. FBD 1953Z. The inspection was conducted on 13/11/2024 at the premises of M/s SG Motors Pte Ltd, 8 Kaki Bukit Avenue 4, #03-03, Premier @ Kaki Bukit, Singapore 415875.

The following vehicle information was recorded:

Registration Number	: FBD 1953Z
Make/Model	: Ducati 848 6SP Manual
Year of Registration	: 2008
Body Colour	: White
Chassis Number	: ZDMH600AA8B007429
Engine Capacity	: 849 cc
Speedometer Reading	: N/A

The vehicle sustained damages at the front portion and o/s body. (Details see photographs enclosed)

- (a) In view of this, we are of the opinion that it would be **unsafe** to proceed with the repairs due to extensive damages on the chassis under the category of **the section 2 of THE ROAD TRAFFIC ACT on THE MOTOR VEHICLES (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989**, that:
no vehicle shall be fitted with a replacement chassis or any body part where the chassis is an integral part of the vehicle.
 and we therefore recommend it to be written off as **“Total Loss”**

Market Value	S\$ 11,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 1,927.00)
Nett Liability	<u>S\$ 9,073.00</u> =====

Vehicle Inspected By:



CHEN TSUE YEE
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.