



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref: CS/AWA24110240/Tqp3m4
(N)

(SINGAPORE BRANCH)

Date: 21/02/2025

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLETREE ANSONSINGAPORE 079914

ATTN: HEW LEE FONG

Code: AWA

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	YN 605K
Policy No.	BVFCB0014792400	Coverage (\$)	0.00
Claim No.	CSG24VFPCA00047/HLF	Excess (\$)	0.00
Assign From	STELLA	Assign Date	12/11/2024

2. Vehicle Particulars & Condition

Make & Model	DULEVO 5000 VELOCE EU4 A (ROAD SWEEPER)	c.c	5880
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	ZA9S5020E4DC38063	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/60R22.5	LING LONG	6 mm
L/H Front Tyre	295/60R22.5	LING LONG	6 mm
R/H Rear Tyre	295/60R22.5	LING LONG	6 mm
L/H Rear Tyre	295/60R22.5	LING LONG	6 mm

4. Description of Damages

THE VEHICLE CAUGHT FIRE. THE CAUSE OF FIRE PROBABLY DUE TO ELECTRICAL IN NATURE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/10/2024	Inspection Date	13/11/2024
Survey held at	18 GUL CRESCENT, SINGAPORE 629527		
Repairer	COMPLETE VMS PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$125,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
--	------------------------