## **INFINITY AUTO 57 PTE. LTD.**

(UEN: 202419522H)
3020A UBI ROAD 1 #01-33, KAMPONG UBI INDUSTRIAL ESTATE, SINGAPORE (408714)
Tel.: +65 9657 5148 Fax: +65 6743 1964

**VEHICLE NO: GBE3307X** 

MAKE/MODEL: NISSAN NV200 1.6AT 2WD

**CHASSIS NO:** VM20082807

	ITEMS:	CONDITION	PRICE	
1	TAILGATE / DD	<u> </u>	\$1,784.50	-
	TAILGATE LOGO / nec		\$64.90	-
	TAILGATE EMBLEM - NV200 / nec		\$69.80	
	TAILGATE EMBLEM / nec		\$61.30	-
	TAILGATE OUTER HANDLE / CUT		\$352.10	- '
	TAILGATE LOCK / BT		\$288.00	٠.
	TAILGATE LOCK COVER x nn		\$21.00	-
	TAILGATE LOCK CATCH x nn		\$36.10	-
	TAILGATE WEATHERSTRIP / CRU		\$88.40	-
	TAILGATE INNER TRIM BOARD x nn		\$298.10	-
	TAILLAMP LH X nn		\$322.70	-
12	TAILLAMP RH x nn		\$322.70	-
	REAR BUMPER / DEF		\$486.60	-
	REAR BUMPER TOW COVER X nn		\$38.20	-
	REAR BUMPER SPONGE X nn		\$119.70	-
16	REAR BUMPER SIDE RETAINER LH / BR		\$37.20	-
	REAR BUMPER SIDE RETAINER RH / BR		\$37.20	-
18	END PANEL TOP GARNISH x nn		\$80.70	
	END PANEL OUTER / DD		\$223.80	/
	END PANEL INNER X R		\$576.00	- 1
21	REAR EXHAUST PIPE x nn		\$632.10	
22	REAR EXHAUST MOUNTING x nn		\$52.50	
23	SPARE TYRE CARRIER x nn		\$297.30	
24	SPARE TYRE CARRIER BRACKET X nn		\$69.10	
25	REAR FENDER LH X R	REPAIR	-	
	SUB-TOTAL \$6,360.00			
		LESS 10% DISCOUNT	\$636.00	3030
	PART TOTAL \$5,724.00			
	SPECIAL NETT:		. ,	
1	SEALANT - REAR WINDSCREEN		\$80.00	40 n
	SEALANT - BODY JOINT		\$80.00	-
	STICKER - 70KM/H		\$20.00	-
	REAR NUMBER PLATE		\$60.00	
	REVERSE SENSOR		Shorted \$250.00	-
	TAILGATE TRIM CLIPS		\$60.00	-
	REAR BUMPER CLIPS		nec \$60.00	-
			,	-

	LABOUR:	
1	TO REMOVE & REFIT REAR WINDSCREEN	\$150.00
2	TO CHECK & RECTIFY WIRING.	\$80.00
3	TO REPLACE REAR PARKING SENSOR & CALIBRATION	\$80.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	\$250.00
5	TO REMOVE & REFIT TAILGATE MECHANISM & FITTING TO ASSIST WORK	\$150.00
6	TO REMOVE & REFIT FLOOR PANEL TRIMING & ATTACHEMENT	\$150.00
7	TO CONDUCT CUT, PANEL BEAT, REPAIR AND REPLACE ACCIDENT AFFECTED ITEMS	\$800.00
8	TO RUST PROOFING	\$30.00
9	PAINWORK ON ACCIDENT AFFECTED AREAS	\$600.00
10	TO REMOVE & REPLACE REAR EXHAUST PIPE	\$120.00
	LABOUR TOTAL	\$2,410.00
	GRAND TOTAL	\$8,744.00

Steve (LKK) 24/06/24 Without Prejudice L/S Resurvey After Spray 6 days

5060.03

L/S - 4048.02= 4050