

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/380, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

*SLU 9139Y  
TP AIG*

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BUILDING  
 SINGAPORE 079120

**TEL:** 64193000  
**ATTN:** Motor Claim Department

**FAX:** 64153727

**WS Ref:** TP/AIG  
**Claim Type:** Third Party  
**Accident Date:** 11/11/2024  
**TP Veh Reg No:** SMF1195D

*Not Withheld  
 21 hrs @ 4250  
 Pending After Rain  
 4 days*

**Estimate No:** ES2400960/WL  
**Date:** 18 Nov 2024  
**Policy No:** DMPG23016384  
**Veh Reg No:** SLU9139Y  
**Make/Model:** TOYOTA TOYOTA  
 HARRIER PREMIUM 2.0  
 CVT  
**Chassis No:** ZSU600104563  
**Engine No:** 3ZRB996060  
**Reg. Date:** 18/12/2017

**Estimate Repair Cost to Vehicle No: SLU9139Y**

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>List Price</b>				
1 REAR BUMPER	2,236.30	1 PC	2,236.30	
2 REAR BUMPER LOWER SKIRT COVER	649.40	1 PC	649.40	
3 REAR BUMPER CLIP	5.50	6 PC	33.00	
4 REAR TAILGATE	2,427.00	1 PC	2,427.00	
5 TAILGATE EMBLEM 'HARRIER'	91.80	1 PC	91.80	
6 REAR WINDSCREEN GLASS MOULDING	220.60	1 PC	220.60	
7 REAR SMART KEY SENSOR	91.70	1 PC	91.70	X
			5,749.80	
		Less 25%:	1,437.45	4,312.35
<b>Special Net</b>				
8 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	
			40.00	40.00
<b>Labour</b>				
9 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
10 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE & ATTACHMENTS; TO KNOCKING & REPAIR REAR PANEL & REALIGN THE SAME	600.00	1 LA	600.00	450
11 PUTTY & RESPRAY ON REAR BUMPER, TAILGATE, REAR PANEL & REAR AFFECTED AREAS	700.00	1 LA	700.00	440
12 REMOVE & REFIX REVERSE CAMERA, SENSOR & SMART KEY SENSOR & RESET SYSTEM	50.00	1 LA	50.00	✓
			1,470.00	1,470.00

**Total** S\$ 5,822.35  
**Add GST @ 9%** 524.01  
**Total Amount Payable** S\$ 6,346.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

**For Cheng Hoe Motor Pte Ltd**

\_\_\_\_\_  
 AUTHORIZED SIGNATURE