

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Tokio Marine Insurance Singapore Ltd
20 McCallum Street, #09-01 Tokio Marine Centre
Singapore 069046

Our File No: CS/TMI24110256/NVP3M4**Date:** 03/12/2024**REFERENCE**

Insured/Claimant:	TAN LAI HUI	Policy No:	MZD04115		
Date of Loss:	08/11/2024	Nature of Claim:	OD	Claim No:	M2406542

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDQ688D	Engine No:	F224H537B38A12A
Make & Model:	MINI ONE, 1.2 5 DOOR (A)	Chassis No:	WMWXS120102G64694
Reg. Date:	05/10/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	S\$47,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/55R16	Rear Tyre Size:	195/55R16
Front Left Side:	Pirelli 0 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12.00	12.00	0.00	0.00
- Excess (S\$)	800.00	800.00	0.00	0.00
Nett Amount (S\$)	-788.00	-788.00	0.00	0.00

INSPECTION

Date of Assignment:	13/11/2024	Present Location:	K Kim Hin Auto Pte Ltd (HQ)
Date Inspected:	14/11/2024	Inspected At:	K. KIM HIN AUTO PTE LTD 160 SIN MING DRIVE, #02-18/19/20/21, SIN MING AUTOCITY, SINGAPORE 575722
Estimated Period of Repair:	0.0 days		

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$47,000.00
OMV :	\$23,251.00
PARF Rebate (1) :	\$ 8,731.00
Quota Premium Paid :	\$42,900.00
COE Rebate (2) :	\$12,403.00
Total Rebate (1) + (2) = :	\$21,134.00

The total amount incurred will be Market Value \$47,000.00 minus Total Rebate \$21,134.00 = \$25,866.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2024)
Parts:	144	MINI ONE 1.2 5 DOOR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDQ688D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >