# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co,Reg,No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: **ECICS** Limited From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

10 Eunos Road 8 #09-04A Singapore Post Centre

Paya Ubi Industrial Park Singapore 408600 Singapore 408933

Attn: Date: 14 Nov 2024

# **Preliminary Advice**

Insured Vehicle No : GBH6202D

TP Vehicle No : SBS3611T Accident Date : 30/10/2024 Make : VOLVO B9TL Assignment Date : 13/11/2024

Date of Inspection : 13/11/2024 Est. Duration of Repair : 5 : STRIDES PREMIER AUTOMOTIVE SERVICES PTE. LTD. (WOODLANDS) Inspection At

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,804.34
Revised Amount	:S\$	3,552.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,552.25

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us
		have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to ( X ) consistency check, part prices and labour cost.