



MOTORSPORTS

JD MOTORSPORTS PTE LTD
25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

*Not Authorized
61 Day @ 5300/-
Presury After Paim
4 days*

DATE : 12/11/2024
VEHICLE : SLJ9373U
MAKE/MODEL : VOLKSWAGEN TOURAN
CHASSIS NO : WVG22211ZHW044806
MILLAGE :
TYRE SIZE :
DOA : 11/11/2024
3RD INSURANCE : BUDGET DIRECT

List items

01 PC	REAR BUMPER	1462.70	add cm	\$ 1,862.00	✓
01 PC	REAR BUMPER DISFUFER	755.20	pd/cm	\$ 1,015.00	✓
01 PC	REAR BUMPER TOWING COVER			\$ 95.80	X
01 PC	REAR BUMPER INNER BRACKET	272		\$ 562.50	✓
01 PC	REAR BUMPER LH LOWER TAIL LAMP BRACKET			\$ 289.10	X
01 PC	REAR BUMPER RH LOWER TAIL LAMP BRACKET			\$ 289.10	X
02 PC	REAR BUMPER SIDE RETAINER @ \$185.20			\$ 370.40	X
01 PC	REAR BUMPER REFELCTOR LH			\$ 211.60	X
01 PC	REAR BUMPER REFELCTOR RH			\$ 211.60	X
01 PC	REAR END PANEL			\$ 1,643.20	X
01 PC	REAR END PANEL TOP GANISH	325.10	mb/cm	\$ 364.30	✓
01 PC	REAR REINFORCEMENT			\$ 853.10	X
01 PC	REAR TAIL GATE	1723.90		\$ 2,361.40	✓
01 PC	REAR TAIL GATE EMBLEM (TOURAN)	126.15		\$ 175.60	—
01 PC	REAR TAIL GATE EMBLEM (280 TSI)	136		\$ 185.30	—
01 PC	REAR TAIL GATE INNER LOCK	133		\$ 632.50	—
01 PC	REAR TAIL GATE INNER TRIM BOARD			\$ 833.90	✓
TOTAL PARTS COST				\$ 11,956.40	

SPECIAL NETT:

02 PC	PARKING SENSOR @ \$380.00		pd	\$ 760.00	400 SN
06 PC	REAR BUMPER CLIP @ \$12.00		na	\$ 72.00	50 SN
06 PC	REAR BUMPER DISFUFER CLIP @ \$12.00		na	\$ 72.00	40 SN
10 PC	REAR TAIL GATE INNER TRIM CLIP @ \$12.00		na	\$ 120.00	X
01 PC	WINDSCREEN SEALANT			\$ 80.00	40 SN
01 PC	PANEL SEALANT			\$ 60.00	X
01 PC	NUMBER PLATE		sn	\$ 30.00	X
01 PC	NUMBER PLATE COVER		sn	\$ 20.00	X
TOTAL SPECIAL NETT				\$ 1,214.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$ 1,000.00	500
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$ 600.00	400
3. TO SUPPLY DIAGNOTIC & RESET FAULT CODE TO FACILITATE THE REPAIR	\$ 250.00	X 50
4. TO SUPPLY LABOUR TO DISMANTLE & REFIX INNER UPHOLSTER	\$ 200.00	120
5. TO SUPPLY LABOUR TO DISMANTLE & REFIX REAR WINDSCREEN	\$ 250.00	20
6. TO SUPPLY LABOUR TO REWIRE ACCIDENT AFFECT AREA	\$ 150.00	20
TOTAL LABOUR		\$ 2,450.00

TOTAL PARTS
TOTAL SPECIAL NETT
TOTAL LABOUR
TOTAL COST OF REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No third party identification(s) is allowed
- Supplies for any item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date

\$ 11,956.40
\$ 1,214.00
\$ 2,450.00
\$ 15,620.40