





# MOTORSPORTS

JD MOTORSPORTS PTE LTD  
25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 12/11/2024  
 VEHICLE : SLJ9373U  
 MAKE/MODEL : VOLKSWAGEN TOURAN  
 CHASSIS NO : WVG22211ZHW044806  
 MILLAGE :  
 TYRE SIZE :  
 DOA : 11/11/2024  
 3RD INSURANCE : BUDGET DIRECT

*Not Authorized*  
*11 Rep &*  
*Mercury After Painting*  
*4-5 days*

### List items

QTY	DESCRIPTION	UNIT	PRICE	TOTAL	REMARKS
01	PC	REAR BUMPER	\$ 1,862.00		✓
01	PC	REAR BUMPER DISFUFER	\$ 1,015.00		✓
01	PC	REAR BUMPER TOWING COVER	\$ 95.80		X
01	PC	REAR BUMPER INNER BRACKET	\$ 562.50		?
01	PC	REAR BUMPER LH LOWER TAIL LAMP BRACKET	\$ 289.10		X
01	PC	REAR BUMPER RH LOWER TAIL LAMP BRACKET	\$ 289.10		X
02	PC	REAR BUMPER SIDE RETAINER @ \$185.20	\$ 370.40		X
01	PC	REAR BUMPER REFELCTOR LH	\$ 211.60		X
01	PC	REAR BUMPER REFELCTOR RH	\$ 211.60		X
01	PC	REAR END PANEL	\$ 1,643.20		?
01	PC	REAR END PANEL TOP GANISH	\$ 364.30		?
01	PC	REAR REINFORCEMENT	\$ 853.10		?
01	PC	REAR TAIL GATE	\$ 2,361.40		✓
01	PC	REAR TAIL GATE EMBLEM (TOURAN)	\$ 175.60		—
01	PC	REAR TAIL GATE EMBLEM (280 TSI)	\$ 185.30		—
01	PC	REAR TAIL GATE INNER LOCK	\$ 632.50		—
01	PC	REAR TAIL GATE INNER TRIM BOARD	\$ 833.90		?
<b>TOTAL PARTS COST</b>			<b>\$ 11,956.40</b>		

### SPECIAL NETT:

02 PC	PARKING SENSOR @ \$380.00	\$ 760.00	✓
06 PC	REAR BUMPER CLIP @ \$12.00	\$ 72.00	501m
06 PC	REAR BUMPER DISFUFER CLIP @ \$12.00	\$ 72.00	401m
10 PC	REAR TAIL GATE INNER TRIM CLIP @ \$12.00	\$ 120.00	X
01 PC	WINDSCREEN SEALANT	\$ 80.00	401m
01 PC	PANEL SEALANT	\$ 60.00	?
01 PC	NUMBER PLATE	\$ 30.00	X
01 PC	NUMBER PLATE COVER	\$ 20.00	X
<b>TOTAL SPECIAL NETT</b>			<b>\$ 1,214.00</b>

### Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$ 1,000.00	?
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$ 600.00	400l
3. TO SUPPLY DIAGNOTIC & RESET FAULT CODE TO FACILITATE THE REPAIR	\$ 250.00	?
4. TO SUPPLY LABOUR TO DISMANTLE & REFIX INNER UPHOLSTER	\$ 200.00	?
5. TO SUPPLY LABOUR TO DISMANTLE & REFIX REAR WINDSCREEN	\$ 250.00	120l
6. TO SUPPLY LABOUR TO REWIRE ACCIDENT AFFECT AREA	\$ 150.00	20l
<b>TOTAL LABOUR</b>		<b>\$ 2,450.00</b>

**TOTAL PARTS**  
**TOTAL SPECIAL NETT**  
**TOTAL LABOUR**  
**TOTAL COST OF REPAIR**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

\$ 11,956.40  
 \$ 1,214.00  
 \$ 2,450.00  
**\$ 15,620.40**