



# MOTORSPORTS

JD MOTORSPORTS PTE LTD  
25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

*Not Authorized  
61 Rep @ 5300/-  
The way After Painy  
4 days*

DATE : 12/11/2024  
VEHICLE : SLJ9373U  
MAKE/MODEL : VOLKSWAGEN TOURAN  
CHASSIS NO : WVG22211ZHW044806  
MILLAGE :  
TYRE SIZE :  
DOA : 11/11/2024  
3RD INSURANCE : BUDGET DIRECT

List items

01 PC	REAR BUMPER	1462.70	Ddl/cm	\$ 1,862.00	✓
01 PC	REAR BUMPER DISFUFR	755.20	pd/cn	\$ 1,015.00	✓
01 PC	REAR BUMPER TOWING COVER		\$ 95.80	X	
01 PC	REAR BUMPER INNER BRACKET	272	\$CM	562.50	✓
01 PC	REAR BUMPER LH LOWER TAIL LAMP BRACKET		\$ 289.10	X	
01 PC	REAR BUMPER RH LOWER TAIL LAMP BRACKET		\$ 289.10	X	
02 PC	REAR BUMPER SIDE RETAINER @ \$185.20		\$ 370.40	X	
01 PC	REAR BUMPER REFELCTOR LH		\$ 211.60	X	
01 PC	REAR BUMPER REFELCTOR RH		\$ 211.60	X	
01 PC	REAR END PANEL		\$ 1,643.20	X	
01 PC	REAR END PANEL TOP GANISH	325.10	mg/cm	\$ 364.30	✓
01 PC	REAR REINFORCEMENT		\$ 853.10	X	
01 PC	REAR TAIL GATE	1723.90	By	\$ 2,361.40	✓
01 PC	REAR TAIL GATE EMBLEM (TOURAN)	126.15	mc	\$ 175.60	—
01 PC	REAR TAIL GATE EMBLEM (280 TSI)	136	mc	\$ 185.30	—
01 PC	REAR TAIL GATE INNER LOCK	133	\$ pd	\$ 632.50	—
01 PC	REAR TAIL GATE INNER TRIM BOARD		mg/cm	\$ 833.90	✓
<b>TOTAL PARTS COST</b>				<b>\$ 11,956.40</b>	

SPECIAL NETT:

02 PC /	PARKING SENSOR @ \$380.00	pd	\$ 760.00	4 2005N
06 PC	REAR BUMPER CLIP @ \$12.00	mc	72.00	505N
06 PC	REAR BUMPER DISFUFR CLIP @ \$12.00	mc	72.00	405N
10 PC	REAR TAIL GATE INNER TRIM CLIP @ \$12.00	mc	120.00	X
01 PC	WINDSCREEN SEALANT	\$	80.00	405N
01 PC	PANEL SEALANT	\$ NN	60.00	X
01 PC	NUMBER PLATE	\$m	30.00	X
01 PC	NUMBER PLATE COVER	\$m	20.00	X
			<b>\$ 1,214.00</b>	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$ 1,000.00	500
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$ 600.00	400
3. TO SUPPLY DIAGNOTIC & RESET FAULT CODE TO FACILITATE THE REPAIR	\$ 250.00	X 50
4. TO SUPPLY LABOUR TO DISMANTLE & REFIX INNER UPHOLSTER	\$ 200.00	
5. TO SUPPLY LABOUR TO DISMANTLE & REFIX REAR WINDSCREEN	\$ 250.00	120
6. TO SUPPLY LABOUR TO REWIRE ACCIDENT AFFECT AREA	\$ 150.00	20
		<b>\$ 2,450.00</b>

**TOTAL PARTS**  
**TOTAL SPECIAL NETT**  
**TOTAL LABOUR**  
**TOTAL COST OF REPAIR**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

\$ 11,956.40  
\$ 1,214.00  
\$ 2,450.00  
**\$ 15,620.40**