

Name & Address:

Motor Claims Department
FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Vehicle No:

SMZ666M

Date:

16-Dec-24

Brand & Model:

BMW M5

Franchise:

BMW

Email/Fax No:

Contact No:

Chassis/VIN No:

WBSJF02090GA03336

Contact Person (Eurokars):

HUI WEN

Type of Claim:

THIRD PARTY

YEAR MODEL:

09/10/2018

WIP#:

30048

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER	51 12 8073725	1		\$ 1,731.95	\$ 1,731.95
2	FLAP, TOWING	51 12 8073380	1		\$ -	\$ 69.00
3	REAR CENTER SUPPORT	51 12 8065846	1		\$ -	\$ 158.05
4	LOWER BUMPER COVER	51 12 8073379	1		\$ 428.85	\$ 428.85
5	GUIDE, CENTER	51 12 8067762	1		\$ -	\$ 227.85
6	GUIDE, REAR LH	51 12 8066721	1		\$ -	\$ 265.80
7	GUIDE, REAR RH	51 12 8066722	1		\$ -	\$ 244.10
8	EXPANDING RIVET	51 47 1911992	6		\$ 7.20	\$ 7.20
9	EXPANDING NUT	63 12 1374075	2		\$ 1.10	\$ 1.10
10	PLUG-IN NUT	51 41 6989691	2		\$ 3.00	\$ 3.00
11	CENTER LOWER SPOILER	51 12 8069482	1		\$ 359.60	\$ 359.60
12	REAR REINFORCEMENT	51 12 7387334	1		\$ -	\$ 974.75
13	SEAL	51 12 5A7CEA6	2		\$ -	\$ 9.70
14	REVERSE SENSOR	66 20 2409650	2		\$ -	\$ 808.50
15	SENSOR SEAL	66 20 9283203	6		\$ 33.90	\$ 33.90
16	REFLECTOR, LH	63 14 7857005	1		\$ -	\$ 45.70
17	REFLECTOR, RH	63 14 7857006	1		\$ -	\$ 45.70
18	TAILPIPE TIP	18 10 8072035	2		\$ 469.70	\$ 469.70
19	REAR MUFFLER	18 30 7883599	1		\$ -	\$ 4,134.60
20	CLAMPING BUSH	18 30 7560815	2		\$ -	\$ 152.10
21						\$ -

Sub-Total (Parts Price) \$ 3,035.30 \$ 10,171.15

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER, REAR REINFORCEMENT AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 850.00	\$ 2,125.00
2	TO RESPRAY REAR BUMPER.	\$ 1,000.00	\$ 1,550.00

3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	\$ -	\$ 850.00
4	TO TRANSFER THE REVERSE SENSORS.	\$ 250.00	\$ 500.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 500.00	\$ 500.00
7	SUNDRIES.	\$ 20.00	\$ 50.00

Survey Date & Time:	Repair Days: 3 Days	Excess:
---------------------	----------------------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	\$ 2,770.00	\$ 5,825.00
	REVISED	PRICE
Parts Price	\$ 3,035.30	\$ 10,171.15
Labour Price	\$ 2,770.00	\$ 5,825.00
Total (Initial Estimate)	\$ 5,805.30	\$ 15,996.15
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ 5,805.30	\$ 15,996.15
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ 5,805.30	\$ 15,996.15
GST 9%	\$ 522.48	\$ 1,439.65
GRAND TOTAL	\$ 6,327.78	\$ 17,435.80