

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Website : www.leeshengauto.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : PAYNOW UEN 201000701R

Messrs. LAND ENGINEERING PTE LTD

30 Kaki Bukit Rd 3,

#04-16 Empire Technocentre Singapore 417819

Attention : Motor Claim Department

Contact : 85057789

Estimate : ES002462

Date : 09/11/2024

Vehicle Num. : GBK 4040 B

Make/Model : NISSAN NV200 1.5L MT ABS-2020

Chassis/Eng# : JN1YAAM20Z0001109

Accident Date : 01/10/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1pc	FRONT BUMPER		
2.	1pc	FRONT BUMPER REINFORCEMENT		450.00
3.	1pc	TOWING COVER		350.00
4.	1pc	FRONT BUMPER RETAINER LH		35.00
5.	1pc	FRONT BUMPER RETAINER RH		35.00
6.	1pc	FOG LAMP BRACKET RH		35.00
7.	1pc	FOG LAMP RH		75.00
8.	1pc	HEADLAMP LOWER PANEL RH		220.00
9.	1pc	HEAD LAMP RH		150.00
10.	1pc	FRONT FENDER RH		400.00
11.	1p	FRONT GRILLE		220.00
List Total S\$:				1,630.00

LABOUR :

KNOCKING, JACKING, WELDING ETC

SPRAY PAINTING ON FRONT FENDER, HEADLAMP LOWER PANEL

WIRING

WHEEL ALIGNMENT

Labour Total S\$:

Total S\$:

LEE SHENG AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for a resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Adm
in
means 90076608

15/11/24

2/5 #1900
2 days

Zhu phl-ATA up

p-2035
102
1831.50
550
2381.5
202
1905