

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3149/06/24

Your Ref:

Date: 26th June 2024

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00, S(048580)

Name Of Insured : Mr Ang See Wan
Date Of Accident : 24/06/24 (13:30hrs)
Policy Number : D22MPC0007781_01

Not Authorized
him
was
28/6/24
4 hrs
1/55
Wright. The 1st.

Estimate cost of repair to TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SCK 8838 D

1 pc boot lid o/s reflector	CN	\$	391.70	/
1 pc boot lid lock	SN		432.50	X
1 pc boot lid 'Corolla Altis' emblem	nm		93.80	/
1 pc boot lid weatherstrip			190.10	?
1 pc boot lid lock stricker	11		29.20	X
1 pc rear bumper	De		620.60	/
10 pcs rear bumper clips	nm	@ \$	5.70	57.00
2 pcs rear bumper o/s & n/s top retainer	11	@ \$	65.60	131.20
2 pcs rear bumper o/s & n/s side retainer		@ \$	119.30	238.60
1 pc rear bumper reinforcement			432.50	?
2 pcs rear bumper reinforcement o/s & n/s stay		@ \$	86.20	172.40
1 set rear bumper reverse sensor (Original)	CN		398.40	/
1 set rear bumper reverse sensor holder		@ \$	54.90	109.80
1 pc rear end panel			727.70	?
1 pc rear end panel top garnish			261.60	?
6 pcs rear end panel top garnish clips		@ \$	6.20	37.20

Less 25%
\$ 4,324.30
\$ 1,081.08

\$ 3,243.22

1 pc rear number plate & frame

SN 50.00 S.N X

To wiring check up for affected wiring system.

60.00 20

To remove & refix carpet, floor board cover, floor mat, garnish, spare tyre, tool set & necessary parts.

120.00 60

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear end panel & necessary parts, to weld, renew & align above parts.

1,100.00 600

To putty & respray painting on all affected accident parts.

1,300.00 600

\$ 5,873.22
=====

Dollars : Five Thousand Eight Hundred Seventy Three And Cents Twenty Two Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To clearly damaged parts, before repair
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: