



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 5737986

HP: 98888885

Estimation

Date: 15/11/2024

Vehicle: SMQ7625H

Make / Model: TOYOTA PRIUS

No.	Description	Unit	Unit Price	Amount
1	BONNET X R	1	\$ 989.00	\$ 989.00
2	FRONT BUMPER / BR	1	\$ 798.00	\$ 798.00
3	FRONT BUMPER LOWER X nn	1	\$ 651.00	\$ 651.00
4	FRONT BUMPER LOGO / MC	1	\$ 68.00	\$ 68.00
5	FRONT BUMPER SIDE RETAINER RH / BR	1	\$ 58.00	\$ 58.00
6	FRONT BUMPER BRACKET RH / BR	1	\$ 52.00	\$ 52.00
7	FRONT BUMPER SPONGE X nn	1	\$ 215.00	\$ 215.00
8	FRONT BUMPER REINFORCEMENT X nn	1	\$ 412.00	\$ 412.00
9	FRONT BUMPER SIDE GARNISH LH X nn	1	\$ 212.00	\$ 212.00
10	FRONT BUMPER DAYLIGHT RH / BR	1	\$ 312.00	\$ 312.00
11	FRONT BUMPER DAYLIGHT WIRE HARNESS X nn	1	\$ 498.00	\$ 498.00
12	FRONT BUMPER UNDER COVER X nn	1	\$ 352.00	\$ 352.00
13	FRONT SUPPORT PANEL X R	1	\$ 1,125.00	\$ 1,125.00
14	FRONT SUPPORT PANEL TOP GARNISH X nn	1	\$ 258.00	\$ 258.00
15	FRONT WIPER WASHER TANK / CPY	1	\$ 358.00	\$ 358.00
16	HEADLAMP / BR (RH)	2	\$ 2,591.00	\$ 5,182.00
17	HEADLAMP LOWER BRACKET RH X nn	1	\$ 42.00	\$ 42.00
18	FRONT FENDER RH / DD	1	\$ 612.00	\$ 612.00
19	FRONT FENDER COWLING RH / CPY	1	\$ 212.00	\$ 212.00
20	FRONT FENDER EMBLEM RH / MC	1	\$ 45.00	\$ 45.00
21	FRONT FENDER WHEEL HOUSING RH X nn	1	\$ 1,258.00	\$ 1,258.00
22	RADIATOR X nn	1	\$ 1,287.00	\$ 1,287.00
23	WIPER WASHER TANK X nn	1	\$ 398.00	\$ 398.00
24	FRONT KNUCKLE ARM RH / BT	1	\$ 598.00	\$ 598.00
25	FRONT KNUCKLE BEARING RH / Jammed	1	\$ 221.00	\$ 221.00
26	FRONT LOWER ARM RH x nn	1	\$ 498.00	\$ 498.00
27	FRONT SHCOK ABSORBER RH x nn	1	\$ 452.00	\$ 452.00
30	FRONT DOOR RH X R	1	\$ 1,025.00	\$ 1,025.00
				\$ 18,188.00
			Less 25%	\$ 4,547.00
			Total	\$ 13,641.00
	S/Nett items:			
1	FRONT WHEEL HUB CAP RH / BR	1	\$ 100.00	\$ 100.00
2	FRONT RIM RH X R	1	\$ 500.00	\$ 500.00
3	FRONT BUMPER CLIPS SET / MC	1	\$ 50.00	\$ 50.00
4	FRONT FENDER COWLING CLIP SET / MC	1	\$ 50.00	\$ 50.00
5	FRONT SUPPORT TOP GARNISH CLIP SET X nn	1	\$ 30.00	\$ 30.00
				\$ 1,570.00

566 /

199 /
2591 /

5534
-25%
4150.50

301
201

150

Labour to:					
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 150.00	\$ 150.00	3 rd
2	REALIGN HEADLAMP	1	\$ 50.00	\$ 50.00	2 nd 25
3	REMOVE AND REPAIR FRONT UNDERCARRIAGE	1	\$ 300.00	\$ 300.00	100
4	CONDUCT WHEEL ALIGNMENT	1	\$ 150.00	\$ 150.00	50
5	TO REMOVE AND REFIT FRONT DOOR MECHANISM	1	\$ 100.00	\$ 100.00	X
6	AND RENEW FRONT SUPPORT PANEL, RADIATOR, CONDENSER	1	\$ 300.00	\$ 300.00	X
7	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	30
8	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00	800
9	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,000.00	600
				\$ 3,250.00	
			Parts Replacement Amount	\$ 15,211.00	1665
			Total Amount for Labour	\$ 3,250.00	
			Total Amount	\$ 18,461.00	

5th CLKK)

15/11/24, 10.12.24

W IL

L/S

by AC by
5 days

5965.50

L/S - 4772.40
= 4750

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____