



DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408819
TEL: 6668 1122 | FAX: 6668 1123

Steve CLKK)
14/11/24, 4.17pL
m n
L/S

QUOTATION

QUOTATION FOR

NAME: Auto & General Insurance (Singapore)
Pte. Ltd
COMPANY NAME: Auto & General Insurance (Singapore)
Pte. Ltd
STREET ADDRESS: 190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
POSTAL CODE: Singapore 239924
PHONE: 6221 2111

DATE: 13/11/2024

REF: SD0824BC0003

VEHICLE NO: SMU1580X

MAKE: HONDA

MODEL: VEZEL

PREPARED BY: XIANG

6 days (not include end pay)

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REPLACE BUMPER FRONT, HEADLAMPS, BONNET, BUMPER REINFORCEMENT, TAILGATE, TAILAMPS, BUMPER REAR, REAR PANEL, BOOT FLOOR & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$1,800.00	\$ 1,800.00		\$ 1,800.00
2	TO SPRAY BUMPER FRONT, BONNET, BUMPER REINFORCEMENT, TAILGATE, BUMPER REAR, REAR PANEL & BOOT FLOOR	1		\$1,700.00	\$ 1,700.00		\$ 1,700.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$200.00	\$ 200.00		\$ 200.00
4	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$200.00	\$ 200.00		\$ 200.00
5	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$150.00	\$ 150.00		\$ 150.00
6	TO REMOVE & REFIT WINDSCREEN REAR	1		\$150.00	\$ 150.00		\$ 150.00
7	TO TRANSFER SENSORS REAR	1		\$100.00	\$ 100.00		\$ 100.00
PARTS							
1	BUMPER FRONT COVER / DEF	1		\$801.70	\$ 801.70		\$ 801.70
2	BUMPER CLIPS - MC	10		\$4.20	\$ 42.00		\$ 42.00
3	BUMPER SIDE RETAINER LH - BR	1		\$20.60	\$ 20.60		\$ 20.60
4	BUMPER SIDE RETAINER RH X	1		\$20.60	\$ 20.60		\$ 20.60
5	HEADLAMP ASSY LH - BR	1		\$2,108.50	\$ 2,108.50		\$ 2,108.50
6	HEADLAMP ASSY RH X	1		\$2,108.50	\$ 2,108.50		\$ 2,108.50

800

1000

30

X

30

120

30

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
7	GRILLE FRONT to 1442228 ?	1		\$351.80	\$ 351.80		\$ 351.80
8	GRILLE FRONT MOULDING (CHROME) (12mm) - BK	1		\$385.10	\$ 385.10		\$ 385.10
9	GRILLE BADGE (LOGO) - NK	1		\$27.80	\$ 27.80		\$ 27.80
10	BONNET - ON	1		\$892.30	\$ 892.30		\$ 892.30
11	BONNET HINGE LH X	1		\$65.80	\$ 65.80		\$ 65.80
12	BONNET HINGE RH X	1		\$65.80	\$ 65.80		\$ 65.80
13	GRILLE FRONT CENTRE MOULDING (CHROME) - BK	1		\$95.20	\$ 95.20		\$ 95.20
14	BUMPER REINFORCEMENT FRONT ?	1		\$321.80	\$ 321.80		\$ 321.80
15	BUMPER SHOCK ABSORBER FRONT ?	1		\$150.00	\$ 150.00		\$ 150.00
16	AIRCOND CONDENSER X	1		\$568.20	\$ 568.20		\$ 568.20
17	NUMBER PLATE FRONT - BK	1		\$25.00	\$ 25.00		\$ 25.00
18	NUMBER PLATE FRONT HOLDER - BK	1		\$30.00	\$ 30.00		\$ 30.00
19	TAILGATE - ON	1		\$1,100.90	\$ 1,100.90		\$ 1,100.90
20	TAILGATE LOCK ?	1		\$178.20	\$ 178.20		\$ 178.20
21	TAILGATE STRIKER X	1		\$38.30	\$ 38.30		\$ 38.30
22	TAILGATE BADGE (LOGO) 22222 ?	1		\$22.50	\$ 22.50		\$ 22.50
23	TAILGATE BADGE (VEZEL) - NK	1		\$68.20	\$ 68.20		\$ 68.20
24	TAILGATE BADGE (HYBRID) - NK	1		\$70.50	\$ 70.50		\$ 70.50
25	TAILAMP OUTER LH ?	1		\$513.20	\$ 513.20		\$ 513.20
26	TAILAMP OUTER RH ?	1		\$513.20	\$ 513.20		\$ 513.20
27	TAILAMP INNER LH ?	1		\$449.50	\$ 449.50		\$ 449.50
28	TAILAMP INNER RH ?	1		\$449.50	\$ 449.50		\$ 449.50
29	TAILGATE APERTURE WEATHERSTRIP ?	1		\$107.80	\$ 107.80		\$ 107.80
30	TAILGATE COVERBOARD ?	1		\$215.30	\$ 215.30		\$ 215.30
31	COVERBOARD CLIPS ?	10		\$4.20	\$ 42.00		\$ 42.00
32	BUMPER REAR COVER LH - CR4	1		\$195.00	\$ 195.00		\$ 195.00

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
33	BUMPER REAR COVER RH X	1		\$195.00	\$ 195.00		\$ 195.00
34	BUMPER REAR LOWER COVER / 00	1		\$532.10	\$ 532.10		\$ 532.10
35	REFLECTOR REAR LH ?	1		\$182.50	\$ 182.50		\$ 182.50
36	REFLECTOR REAR RH X	1		\$182.50	\$ 182.50		\$ 182.50
37	REAR PANEL ?	1		\$411.90	\$ 411.90		\$ 411.90
38	REAR PANEL INNER TRIM ?	1		\$92.30	\$ 92.30		\$ 92.30
39	BOOT FLOOR CARPET ?	1		\$325.60	\$ 325.60		\$ 325.60
40	BOOT FLOOR TRAY ?	1		\$226.90	\$ 226.90		\$ 226.90
41	WINDSCREEN MOULDING REAR / MK	1		\$120.70	\$ 120.70		\$ 120.70
42	EXHAUST SILENCER REAR X	1		\$726.30	\$ 726.30		\$ 726.30
43	BOOT FLOOR ?	1		\$1,135.70	\$ 1,135.70		\$ 1,135.70
44	MOULDING WHEEL ARCH REAR LH / (RM)	1		\$292.10	\$ 292.10		\$ 292.10
45	MOULDING WHEEL ARCH REAR RH X	1		\$292.10	\$ 292.10		\$ 292.10
46	SENSOR BUMPER REAR (SET) / BR	1		\$135.00	\$ 135.00		\$ 135.00
47	AIRCOND GAS X	1		\$80.00	\$ 80.00		\$ 80.00
48	FLOOR BOARD SEALANT ?	1		\$100.00	\$ 100.00		\$ 100.00
49	WINDSCREEN SEALANT (PWR) / MK	1		\$80.00	\$ 80.00		\$ 80.00
SUBTOTAL					\$ 21,455.50	SUBTOTAL	\$ 21,455.50
GST 9%					\$ 1,931.00	GST 9%	\$ 1,931.00
TOTAL					\$ 23,386.50	TOTAL	\$ 23,386.50

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: