



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: BETTY WONG		Ref: CS/FCI24110293/Tnp3e2(N) Date: 06/05/2025 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 466D	Veh. Inspected	FBC 7023Z
Policy No.	D-24101860MFCT	Coverage (\$)	0.00
Claim No.	D24008103MFCT	Excess (\$)	0.00
Assign From	BETTY WONG	Assign Date	13/11/2024
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	SUZUKI DRZ400	c.c	398
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	SK44A104819	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	120/70 R17	BRIDGESTONE	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/60 R17	BRIDGESTONE	5 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	13/09/2024	Inspection Date	13/11/2024
Survey held at	PANG SCOOTER SERVICE BLK 1006 BUKIT MERAH LANE 2 #01-06 SINGAPORE 159762		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	