



Champion Motors

Co. Reg No. : 195000068E
GST Reg No. : MR-8500000-9
No. 2 Pandan Crescent
Singapore 128462 Tel: 66311855



ESTIMATE

Account Details			Account No.		Customer Details			
India International Insurance Pte Ltd 64 Cecil Street #06-02 IOB Building Singapore 049711			S8000010 / WII1		Mr Gay Kim Cheok Roland 15 Flora Road #03-06 Singapore 509734 Mobile: 96667398			
			Document No. 0					
			Document Date 14/11/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2021	SWIFT	2LC4C9F35	27/04/2021	SFS2561M	0	12479	79/DS/SFS2561M	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JSAAZCA3S00523334		K12D1099077	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:III TP VEH:GBL7319Z DATE OF ACC:13/11/2024 NUMBER OF REPAIR DAYS: SURVEY BY:				100.00		100.00
2	B	BP-AI2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS				1296.00		1296.00
3	B	BP-AI2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS				1072.44	0.04	1072.00
4	B	BP-AI2 TO CHECK WIRING SYSTEM				110.16		110.16
5	B	BP-AI2 TO DRILL HOLE AND INSTALL REVERSE SENSOR				162.00		162.00
6	B	BP-AI2 TO RESET ECU AND REPROGRAMME				162.00		162.00
7	1	S71811-53R50-799 BUMPER,REAR(PRIMARY)			1.00	778.30		778.30
8	2	S09409-08327-000 CLIP			10.00	2.60		26.00
9	3	S71821-53R00-000 HOLDER,RR BUMPER SIDE,R			1.00	8.00		8.00
10	4	S71822-53R00-000 HOLDER,RR BUMPER SIDE,L			1.00	8.00		8.00
11	5	S3F115-79S00-ZNC SNSR ASSY,AUTO BK RR(SILVER)			2.00	75.70		151.40
12	6	S3F117-79S00-000 BRACKET,AUTO BRAKE RR			4.00	81.45		325.80
For & on behalf of Champion Motors (1975) Pte Ltd			Customer's Signature		Charge Summary		Total 4,199.66	
			Please acknowledge receipt of vehicle		Parts 1,297.50		GST 9.00% 377.97	
					Labour 2,902.16			
					Sublet 0.00			
					Lubrication/Fluid 0.00		Less 0.00	
					Others 0.00		Amount Due 4,577.63	

Customer Copy