

Automobile Integrated Management Pte Ltd (Co.Reg.No:201605297G)

3021A Ubi Road 1, #01-42

Singapore 408715

Tel: 91198371 Email: automim.claim@gmail.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	C20240098/OD
Policy No:	MPC24A00143401	Date of Loss:	08/11/2024
Vehicle Reg. No.:	SJP8295K	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG EE SIN		
Make/Model:	CHEVROLET CAPTIVA, 2.4 (A)	Vehicle Reg. Date:	14/04/2009
Vehicle Colour:	WHITE		
Engine No:	Z24SED037891	Chassis No:	KL1CD26F18B214406
Odometer:	381008 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	8,489.25
Miscellaneous Items	160.00
Labour	1,320.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (\$\$)	10,969.25
+ GST 9.00% (\$\$)	987.23
Nett Amount (\$\$)	11,956.48

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Not Authorised
on
18/11/24
EXCESS nil
L/S \$5800/
whp h. ahm
1 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Nov 2024)
Parts: M1-SUV CHEVROLET CAPTIVA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Automobile Integrated Management Pte Ltd/SJP8295K/13/11/2024 12:09
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		Air-cond condenser	0.00	0.00	*625.00 F 2
2	1		Bonnet	0.00	0.00	*1,062.50 F x
3	1		Bonnet lock	0.00	0.00	*131.25 F
4	10		Bumper clip, front	0.00	0.00	*37.50 F 20
5	1		Bumper fog lamp cover LH	0.00	0.00	*15.00 F
6	1		Bumper fog lamp cover RH	0.00	0.00	*15.00 F
7	1		Bumper fog lamp LH, front	0.00	0.00	*131.25 F 2
8	1		Bumper fog lamp RH, front	0.00	0.00	*131.25 F
9	1		Bumper reinforcement, front	0.00	0.00	*500.00 F
10	1		Bumper, front	0.00	0.00	*687.50 F
11	1		Headlamp LH	0.00	0.00	*1,200.00 F
12	1		Headlamp RH	0.00	0.00	*1,200.00 F
13	1		Radiator	0.00	0.00	*562.50 F
14	1		*Center grille (top) assy	0.00	0.00	*500.00 F
15	1		*Logo emblem	0.00	0.00	*50.00 F
16	1		*Lower grille	0.00	0.00	*250.00 F
17	1		*Front bumper lower	0.00	0.00	*275.00 F
18	1		*Front bumper lower center	0.00	0.00	*225.00 F
19	1		*Support panel top garnish	0.00	0.00	*118.75 F
Sub Total (\$\$)						7,717.50
+ Margin on L,N Items 10.00% (\$\$)						771.75
Total Parts (\$\$)						8,489.25

Automobile Integrated Management Pte Ltd/SJP8295K/13/11/2024 12:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	Air-cond gas (Normal)	60.00
2	1	Number plate, front	40.00
3	1	Radiator coolant	60.00
Sub Total (\$\$)			160.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Spraypaint	New	1,000.00
Labour Items			
2	Wiring	New	120.00
3	Panel beating	New	1,200.00
Gross Labour Cost (\$\$)			2,320.00

Automobile Integrated Management Pte Ltd/SJP8295K/13/11/2024 12:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >