



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24110311/Uqp3m4
(BUDGET DIRECT INSURANCE)	Date:	04/12/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 6246A	Veh. Inspected	SNF 7577J
Policy No.	P10194337R05	Coverage	0
Claim No.	C10032869/CY	Excess	\$0.00
Assign From	CALEEN YIT	Assign Date	15/11/2024

2. Vehicle Details

Make & Model	TOYOTA NOAH HYBRID (A)	C.C	1797
Engine No.	2ZR0D05298	Year of Reg.	02/04/2019
Chassis No.	ZWR800367197	Colour	BLACK
Odometer	71191 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/45ZR17	MICHELIN	6
L/H Front Tyre	215/45ZR17	MICHELIN	6
R/H Rear Tyre	215/45ZR17	MICHELIN	6
L/H Rear Tyre	215/45ZR17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/11/2024	Inspection Date	15/11/2024
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days