

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24110316/Aqh3m4(N)
	75 BRAS BASAH R INCOME CENTRES		Date:	07/05/2025	
	ATTN: CHRYLLIS	QUAH		Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMF 2274C	Veh. Inspected	k	SNA 6646B
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1304193-002	Excess (\$)		0.00
	Assign From	JESS TOH	Assign Date		15/11/2024
2. Vehicle Particulars & Condition					
	Make & Model	BMW 523I	c.c		2497
	Engine No.	HIDDEN	Year of Reg.		2010
	Chassis No.	WBAFP32030C544699	Colour		BLACK
	Odometer	289496 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	245/40R19	HABILEAD		6 mm
	L/H Front Tyre	245/40R19	HABILEAD		6 mm
	R/H Rear Tyre	245/40R19	HABILEAD		6 mm
	L/H Rear Tyre	245/40R19	HABILEAD		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
					£ **
5.	General Information				
	Accident Date	14/11/2024	Inspect Date /	Time	18/11/2024 (02:37 PM)
	Survey held at	JL PERFECT AUTOWORK PTE	LTD		
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		7 Workir	ng Days