

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : YR1472Z

Model:

MIT CANTER

Accident Date : 13/11/2024

27/2/2024

Location : TSCIENCE PARK

3P:

SFF2806B (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front cabin mounting bushing TN	55.00	✓	
2	1 set	Front cabin mounting cushion TN	320.00	280	
3	1 pc	Front cabin mounting Bent	850.00	750	
		Sub Total:	1,225.00	0.00	0.00
			25%	0%	0%
		After Less %:	918.75	0.00	0.00
		Labour			
1		To remove and replace front cabin mounting	300.00	200	
		Sub Total:	300.00		
		Total:	1,218.75		
		After less 20%:	975.00		

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Supplementary: 99875

