FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/67467158 Fax No: 67458520

Tax Reg No: 200006262D

VEHICLE No: SMC 1963U

REAR WINDSCREEN SEALANT

REAR BUMPER CLIPS

REAR END PANEL SEALANT

REAR WINDSCREEN INNER SEAL

REAR BUMPER REVERSE SENSOR

TAILGATE INNER TRIM BOARD CLIPS

REAR BUMPER TOP CHROME PLATE NA

1PC

1PC

1SET

1SET

1SET

1PC

1PC

MI

mel Ruc ton

nu

ru

nu

Not Authoral
means
15/11/24 1

\$50.00 40

\$50.00 20

\$280.00 200

\$50.00 30

\$60.00 30

\$50.00

\$380.00 X

d 1 \$200.00 X \$50.00 20

TO CHECK WIRING
TO DISMANTLE & REPLACED REVERSE SENSOR
TO DISMANTLE & REFIX REAR WINDSCREEN
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
TO TRANSFER TAILGATE MECHANISM
TO SPRAY RUST PROOFING
TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 30 \$150.00 120 \$120.00 60 \$100.006 v \$100.0060 17 \$120.00 X \$1,800.00 800 \$1,800.00 [000 \$21,129.60 TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: