



53 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PAXP/TP/0003/2024/KS
DATE : 18-Nov-24
WIP : 10044

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY 19/11/2024

YOUR INSURED VEHICLE NO : SNF 7602 U

LONPAC INSURANCE Bhd

100 BEACH ROAD

#19-00 SHAW TOWER

SINGAPORE 189702

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

OWNER'S NAME : MR SOONG CHIN KHANG
ADDRESS : 27 FERNVALE ROAD
#22-27
SINGAPORE 797415
TELEPHONE : HP +65 97828858
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7240194396
VEHICLE NO : **SNT 3410 J**
MODEL CODE : XPENG G6 RWD (LONG RANGE)
MODEL YEAR : 26/9/2024
ENGINE NO : E7H5017911030000FA6
CHASSIS NO : L1NNSGHA5RB074127
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Nov-24
PLACE OF ACCIDENT : PUNGGOL CENTRAL (OUTSIDE PARC CENTROS)



53 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SNT 3410 J.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,000.00	
3	TO RESPRAY REAR BUMPER, REAR BUMPER MID, REAR BUMPER SPOILER AND BOTH REAR WHEEL ARCH TRIMS.	\$	4,200.00	
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	480.00	
TOTAL LABOUR CHARGES		:	\$ 7,040.00	



53 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNT 3410 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER UPPER	1	\$ 773.00	
2	REAR BUMPER LOWER	1	\$ 773.00	
3	REAR BUMPER SPOILER	1	\$ 387.00	
4	REAR BUMPER REVERSE \$ FOG LIGHT	1	\$ 248.00	
5	REAR WHEEL ARCH TRIM - LH / RH	2	\$ 350.00	
6	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 3,031.00	
TOTAL LABOUR CHARGES		:	\$ 7,040.00	
GRAND TOTAL		:	\$ 10,071.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT