

C

Kenneth

1074

The U/C / Chassis frame / Body Structure affected due to collision.



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 20/11/2024
VEHICLE : FBL7898T
MAKE/MODEL : YAMAHA SNIPER 150 MX
CHASSIS NO : MH3UG0740G0035520
MILLAGE : 3456KM
TYRE SIZE :
DOA : 5/11/2024
TP INSURANCE : LIBERTY

Not Authorized
11 Sep & 15 Sep
Money After Pain
4 days

List items

01 PC	REAR NUMBER PLATE GARNISH	126	\$ CM	250.00	✓
01 PC	REAR NUMBER PLATE GARNISH BRACKET	53	\$ Bu	80.00	✓
01 PC	REAR NUMBER PLATE LAMP		\$ Bu	60.00	✓
01 PC	REAR SIGNAL LAMP		\$ Lu	45.00	✓
01 PC	REAR BOX		\$ Bu/Lu	450.00	220.00
01 PC	REAR BOX BRACKET		\$ Bu	250.00	X
01 PC	REAR BOX SIDE BRACKET		\$ Bu	200.00	✓
01 PC	REAR SEAT LOCK		\$ R	140.00	X
01 PC	REAR SWING ARM	420	\$ Bu	850.00	2
01 PC	REAR SWING ARM BUSHING	21.60	\$ Lu	120.00	2
01 PC	REAR RIM		\$ Lu	300.00	X
01 PC	REAR CHAIN		\$ Lu	180.00	X
01 PC	REAR SPROCKET		\$ Lu	150.00	X
01 PC	REAR CHAIN COVER		\$ Lu	90.00	X
01 PC	REAR FOOT REST		\$ Lu	40.00	X
01 PC	REAR FOOT REST BRACKET		\$ Lu	90.00	X
01 PC	MAIN STAND ARM		\$ Lu	180.00	X
01 PC	FRONT FOOT REST		\$ Lu	40.00	✓
01 PC	GEAR LIVER PADEL		\$ Lu	45.00	✓
01 PC	ENGINE MAGNET COVER		\$ Lu	150.00	X
01 PC	ENGINE MAGNET COVER GASKET		\$ Lu	25.00	X
01 PC	TAIL FAIRING SET		\$ Lu	200.00	X
01 PC	SIDE FAIRING SET		\$ Lu	250.00	X
01 PC	FRONT FAIRING SET		\$ Lu	200.00	X
01 PC	DASH FAIRING		\$ Lu	150.00	X
01 PC	DASH INNER FAIRING		\$ Lu	150.00	X
01 PC	FRONT BOX		\$ Lu	350.00	X
01 PC	FRONT BOX BRACKET		\$ Lu	80.00	X
01 PC	MIRROR LH		\$ Lu	60.00	✓
01 PC	HEAD LAMP COWLING		\$ Lu	180.00	X
01 PC	CLUTCH LEVER		\$ Lu	30.00	X
01 PC	STERRING CONE		\$ Lu	150.00	X
01 PC	HANDLE BAR		\$ Bu	150.00	2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

01 PC	HANDLE GRIP
01 PC	HANDLE BALANCER
02 PC	FRONT SIGNAL LAMP @ \$120
02 PC	FRONT POLIT LAMP @ \$100
01 PC	FRONT FENDER
01 PC	FRONT FENDER
01 PC	RADIATOR
02 PC	FRONT FORK @ \$100
01 PC	FRONT FORK BRACKET @ \$100

TOTAL PARTS COST

101

\$	Gr	45.00	✓
NJB		60.00	X
\$	Bn	240.00	X
\$	Bn	200.00	X
\$	Bn	160.00	X
\$	Bn	35.00	X
\$	Bn	250.00	X
\$	Bn	200.00	X
\$	Bn	200.00	X
\$		7,075.00	

Special Nett Item:

01 PC	REAR NUMBER PLATE
01 PC	ENGINE OIL
01 PC	REAR TYRES
01 PC	BODY STICKER
01 PC	FORK OIL
01 PC	FORK SEAL
01 PC	O.B.U

246.50 Bn 15 Bn 100

\$	Mit	20.00	15 Bn
\$	nn	60.00	X
\$	nn	150.00	X
\$	nn	200.00	X
\$	nn	60.00	X
\$	nn	60.00	X
\$		380.00	10 Bn.
\$		930.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO STRAIGHTEN BODY
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY LABOUR TO ALIGN FRONT BAR

\$		1,000.00	10 Bn
\$	nn	600.00	X
\$		600.00	100 Bn
\$		200.00	10 Bn
\$	nn	300.00	X
\$		2,700.00	

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

\$	7,075.00
\$	930.00
\$	2,700.00
\$ 10,705.00	