

**BIFROST AUTO PTE LTD**  
 8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT  
 #01-49 SINGAPORE 415875  
 Tel: +65 64524457  
 Fax: +65 64524584

Vehicle number: SNS1972Y  
 Make & Model: Mazda 3  
 Chassis number: JM6BP2SAAR1203229

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet / OD	1	\$ 850.00 /
2	Bonnet RH hinge / BT	1	\$ 55.00 /
3	Bonnet LH hinge / BT	1	\$ 55.00 /
4	Bonnet lock - BT	1	\$ 120.00 /
5	Bonnet lock cable ? / TN	1	\$ 70.00 /
6	Bonnet inner heat insulator / CR#	1	\$ 128.00 /
7	Bonnet inner heat insulator clips - MC	1	\$ 30 / 60.00 /
8	Front bumper / BR	1	\$ 700.00 /
9	Front bumper clips / MC	1set	\$ 30 20 / 60.00 /
10	Front bumper rivets / MC	1set	\$ 20 / 50.00 /
11	Front bumper upper garnish pad / BR	1	\$ 415.00 /
12	Front bumper lower grille / BR	1	\$ 65.00 /
13	Front bumper lower grille RH cover / BR	1	\$ 12.00 /
14	Front bumper lower grille LH cover / BR	1	\$ 12.00 /
15	Front bumper towing cover / MIS	1	\$ 14.00 /
16	Front bumper RH parking sensor ? X nn	1	\$ 150.00 /
17	Front bumper LH parking sensor ? X nn	1	\$ 150.00 /
18	Front bumper parking sensor wire harness ? X nn	1	\$ 330.00 /
19	Front bumper parking sensor holder / MP	2	\$ 40.00 /
20	Front bumper LH fog lamp cover / BR	1	\$ 60.00 /
21	Front bumper RH fog lamp cover / BR	1	\$ 60.00 /
22	Front bumper RH side retainer / BR	1	\$ 20.00 /
23	Front bumper LH side retainer / BR	1	\$ 20.00 /
24	Front bumper RH lower bracket / BR	1	\$ 46.00 /
25	Front bumper LH lower bracket / BR	1	\$ 46.00 /
26	Front bumper reinforcement ? / OD	1	\$ 505.00 /
27	Front bumper reinforcement seal strip ? / BR	1	\$ 130.00 /
28	Front bumper lower cover ? X nn	1	\$ 140.00 /
29	Front bumper lower cover clips ? X nn	1set	\$ 50.00 /
30	Front bumper upper inner rubber seal / TN	1	\$ 80.00 /
31	Front bumper number plate garnish / BR	1	\$ 75.00 /
32	RH headlamp assy / BR	1	\$ 1,500.00 /

33	RH headlamp lower bracket	✓ BR	1	\$	50.00
34	LH headlamp assy	✓ BR	1	\$	1,500.00
35	LH headlamp lower bracket	✓ BR	1	\$	50.00
36	Support panel	✓ PD	1	\$	840.00
37	Support panel upper garnish	✓ BR	1	\$	140.00
38	Support panel upper garnish clips	✓ MC	1set	\$ 20	50.00
39	Front temperature sensor	✓ BR	1	\$	110.00
40	Front grille	✓ BR	1	\$	230.00
41	Front grille emblem	✓ PT	1	\$	50.00
42	Front grille LH chrome moulding	✓ BR	1	\$	280.00
43	Front grille LH chrome moulding clips	✓ MC	1set	\$ 15	40.00
44	Front grille RH chrome moulding	✓ BR	1	\$	280.00
45	Front grille RH chrome moulding clips	✓ MC	1set	\$ 15	40.00
46	Front RH fender	✓ R	1	\$	380.00
47	Front RH fender splash shield	× nn	1	\$	60.00
48	Front RH fender splash shield clips	× nn	1set	\$	40.00
49	Front LH fender	✓ PD	1	\$	380.00
50	Front LH fender splash shield	✓ TM	1	\$	60.00
51	Front LH fender splash shield clips	✓ MC	1set	\$ 20	40.00
52	Wiper tank	× nn	1	\$	50.00
53	Wiper tank motor	× nn	1	\$	68.00
54	Wiper garnish RH	× nn	1	\$	124.00
55	Wiper garnish side cover RH	× nn	1	\$	10.00
56	Wiper garnish LH	× nn	1	\$	124.00
57	Wiper garnish side cover LH	× nn	1	\$	10.00
58	Air duct upper	✓ BR	1	\$	60.00
59	Air duct lower	✓ BR	1	\$	55.00
60	Air cleaner box upper	× nn	1	\$	195.00
61	Air cleaner box lower	× nn	1	\$	195.00
62	Fuse box upper	× nn	1	\$	80.00
63	Fuse box lower with harness	× nn	1	\$	850.00
64	Aircon condenser	✓ PD	1	\$	750.00
65	Aircon suction pipe	✓ BT	1	\$	300.00
66	Aircon discharge pipe	✓ BT	1	\$	300.00
67	Aircon liquid pipe	× nn	1	\$	320.00
68	Radiator assy	✓ BT	1	\$	750.00
69	Radiator fan assy	✓ BR	1	\$	400.00
70	Radiator spare tank	✓ CR4	1	\$	125.00
71	Radiator upper hose	× nn	1	\$	70.00
72	Radiator lower hose	× nn	1	\$	70.00
73	Dashboard	✓ BR	1	\$	1,600.00
74	Driver steering airbag	✓ BR	1	\$	1,300.00
75	Driver steering clock sensor	✓ MC	1	\$	400.00
76	Driver leg airbag	✓ BR	1	\$	880.00
77	Driver seat belt	✓ Jem and	1	\$	750.00

11710

78	Driver seat belt buckle	X nn	1	\$	120.00
79	Front LH passenger seat assy	/ DEF	1	\$	3,150.00
80	Front LH passenger airbag	/ BR	1	\$	950.00
81	Front LH passenger seat buckle	X nn	1	\$	120.00
82	Airbag control unit	/ PKC	1	\$	1,100.00
83	Airbag RH sensor	/ PKC	1	\$	250.00
84	Airbag LH sensor	/ PKC	1	\$	250.00
85	Front windscreen glass	/ BR	1	\$	1,300.00
86	Front windscreen glass rubber moulding	/ PKC	1	\$	150.00

7150

\* ~~passenger seat belt - removed~~  
 \* ~~Front panel lower panel - BT~~  
 \* ~~Hybrid battery LH, f, r - BR~~

7 +10%  
 \$ 27,914.00  
 Parts cost +20% \$ 5,582.80  
 Total: \$ 33,496.80

24008  
 +10%  
 26408.8

No.	Special Nett Items	Qty	Amount S\$
1	Front number plate / BR	1	\$ 50 / 70.00
2	Radiator coolant / PKC	1	\$ 30 / 80.00
3	Autogear box fluid (refill) / PKC	1	\$ 50 / 100.00
4	Front windscreen glass sealant / PKC	1	\$ 40 / 80.00
5	Front windscreen glass inner seal / PKC	1	\$ 40 / 60.00
6	Front windscreen glass ERP bracket / PKC	1	\$ 20 / 26.00

Total: \$ 416.00

230

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas * repl chm, LH	\$ 1,800.00
2	Spray painting on affected areas and panels	\$ 1,600.00
3	Check wiring and lighting system on affected areas	\$ 120.00
4	Apply rust coating chemical on affected areas and panels	\$ 100.00
5	Remove and replace front bumper parking sensors, holders	\$ 150.00

1000  
 1200  
 1000  
 50  
 30  
 30



**BIFROST AUTO PTE LTD**  
 8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT  
 #01-49 SINGAPORE 415875  
 Tel: +65 64524457  
 Fax: +65 64524584

*Steve (CLKK)*

*3/12/24, 11.39 am*

Vehicle number: SNS1972Y  
 Make & Model: Mazda 3  
 Chassis number: JM6BP2SAAR1203229

No.	Description of spare parts	Qty	Amount S\$
1	Passenger seat belt / <i>jammed</i>	1	\$ 750.00
2	Front panel lower / <i>oil</i>	1	\$ 370.00
3	Hybrid battery LH / <i>BR</i>	1	\$ 15,000.00

10% \$ 16,120.00  
 Parts cost +20% \$ 3,224.00  
 Total: \$ 19,344.00 17732

No.	Special Nett Items	Qty	Amount S\$

Total: \$ -

No.	Labour and painting	Amount S\$
1	Labour for supplementary	\$ 1,800.00

Total: \$ 1,800.00

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)

Working days: \_\_\_\_\_

Spare Parts: \$ 19,344.00  
 Special Nett: \$ -  
 Labour: \$ 1,800.00

Total: \$ 21,144.00 19532