



> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	705E
<b>Vehicle Details</b>	
Vehicle No.:	SLR1131L
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2024
Vehicle Make:	HONDA
Vehicle Model:	GRACE HYBRID 1.5DX A
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	LEB5255384
Chassis No.:	GM41105369
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,154.00
Original Registration Date:	31 Jul 2017
First Registration Date:	31 Jul 2017
Transfer Count:	1
Actual ARF Paid:	\$5,000.00 2500
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2027
PARF Rebate Amount:	\$3,000.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$12,807.00
<b>Total Rebate Amount:</b>	<b>\$15,807.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 19 Nov 2024

OK

# WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

*Not Authorized*

*for*  
*meas*

18 November 2024

*19/11/24*

*2/5 @ 6500/  
sub plate after repair*

*5 days*

REG NO. : SLR 1131 L  
MAKE/MODEL : HONDA GRACE

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	\$ 11 115.00 X
1	Rear boot lid	\$ 845.00 1,288.90 ✓
1	Rear boot chrome clip (1 set)	\$ 11 75.00 X
1	Rear boot outer chrome moulding	\$ CR 320.30 ✓
1	Rear boot top spoiler	\$ CR 600 1,106.90 ✓
2	Rear boot hinges	\$ 90-20 180.40 1PC
1	Rear boot inner trim	\$ 11 260.80 X
2	Rear boot lamps	\$ CR 783.80 ✓
1	Rear boot inner lock	\$ TW 195.00 ✓
1	Rear boot logo	\$ CR 28.20 ✓
1	Rear boot weatherstrip	\$ TW 129.60 ✓
1	Rear boot "GRACE" emblem	\$ CR 55.60 ✓
1	Rear boot "HYBRID" emblem	\$ CR 68.30 ✓
2	Rear number plate lamps	\$ CR 170.00 ✓
2	Rear taillamps	\$ CR 450x2=900 1,358.80 ✓
2	Rear taillamp panels	\$ 299 890.40 1PC ✓
1	Rear end panel	\$ 600 813.70 ✓
1	Rear end panel inner garnish	\$ TW 215.00 ✓
1	Rear bumper	\$ 632-50 1,000.70 ✓
1	Rear bumper inner sponge	\$ NZ 99.10 X
2	Rear bumper reflectors	\$ 65-30 130.60 1PC
2	Rear bumper side retainers	\$ 11 97.20 X
1	Rear floor panel	\$ R 855.30 X
1	Rear floor board	\$ 394-20 455.00 ✓
1	Rear fender -RH	\$ R 1,414.60 X
2	Rear fender inner trim boards	\$ 394-10 801.80 1PC ✓
		\$ 12,910.00
	Less 20%	\$ 2,582.00
		\$ 10,328.00

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	AM	80.00	X
1	Rear bumper clip (1 set)	\$	AM	80.00	30
1	Rear number plate with holder	\$	SVC	50.00	X
1	Rear reverse sensor (1 set)	\$	modification	350.00	200
1	Rear reverse camera	\$	AM	600.00	X
		\$		<u>1,160.00</u>	

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	20
2	To remove and refit inner garnishes.	\$		150.00	60
3	To remove and refit rear reverse sensor and camera.	\$		150.00	30
4	To transfer boot lid mechanism and wiring assembly.	\$		80.00	50
5	To remove and refit rear windscreen glass.	\$	AM	180.00	X
6	To apply undercoating.	\$		200.00	60
7	Panel beating.	\$		2,000.00	800
8	To re-spray painting on the affected areas.	\$		1,800.00	1200
		\$		<u>4,640.00</u>	

**GRAND TOTAL :**

**\$ 16,128.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-7235  
202  
5788.  
230  
2200