

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,

SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128

Business Regn No: 269436/00J

Not Authorized
11/11/24 @ 3350h
Running After Rain
6 days

20 November 2024

China Taiping Insurance (Singapore) PL

105 Cecil Street

#18-00 The Octagon

Singapore 069534

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: PA5250S

Accident involving vehicle no: GBK6737L/PA5250S

DOA: 11/11/2024 at ANG MO KIO 5 & 6 JUNCTION

Description	Qty	Amount
Rear sliding door LH <i>1890-60</i>	1	<i>R</i> \$1,880.20 ✓
Rear door center roller LH	1	<i>L</i> \$151.90 X
Rear door handle LH	1	<i>R</i> \$169.82 X
Rear fender lower panel LH	1	<i>NIP</i> \$322.90 X
Rear fender LH <i>1875-60</i>	1	<i>R</i> \$2,385.60 ✓
Rear fender cowling LH	1	<i>L</i> \$278.10 X
Rear bumper	1	<i>R</i> \$699.30 X
Rear bumper retainer LH	1	<i>L</i> \$35.80 X
Tailamp LH	1	<i>R</i> \$471.70 X
Tailamp panel	1	<i>R</i> \$142.00 X
Tailamp bracket	1	<i>L</i> \$61.80 X
Parts total		\$6,599.12
less 25%		\$4,949.34

S/Nett Items

Door sticker - Company name

1 *R* \$350.00 *1501N*
1 SET *R* \$340.00 X

Tire rim

Parts total	\$690.00
-------------	-----------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour charger & Misc

Check all wiring and lightning system

\$120.00 201

Panel beating on affected areas and renew damage parts

\$1,000.00 8001

Spray painting on affected areas

\$1,000.00 5001

Apply anti rust on affected areas

\$150.00 601

Labour total

\$2,270.00

Total Parts & Labour

\$7,909.34
