



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNA 2413H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	BROKEN	\$798.00	\$503.00
1	REAR BUMPER SIDE RETAINER RH	BROKEN	\$112.00	\$112.00
1	REAR BUMPER LOWER LID	NOT NECESSARY	\$598.00	\$0.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	\$621.00	\$0.00
1	TAILLAMP RH	NOT NECESSARY	\$512.00	\$0.00
	LESS 25.00% DISCOUNT		(\$660.25)	(\$153.75)
			\$1,980.75	\$461.25

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	REAR WHEEL HUB CAP RH (SN)	NOT NECESSARY	\$100.00	\$0.00
			\$150.00	\$30.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK WIRING		\$100.00	\$30.00
	REMOVE AND REFIT REAR BUMPER SENSOR		\$150.00	\$30.00
	PANEL BEAT EFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH		\$400.00	\$400.00
	RESPARY EFFECTED AREAS		\$600.00	\$400.00
			\$1,250.00	\$860.00

GRAND TOTAL			\$3,380.75	\$1,351.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,100.00

Report Ref No: CS/LIP24110366/Enh3e2

MARKET VALUE: \$110,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$41,768.00=NETT VALUE: \$68,232.00

CTY

STEVE CHEN TSUE YEE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.