

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583		Ref:	CS/LIP24110366/Enh3e2	
			Date:	06/12/2024	
	SINGAL ONE 04030	33	Code:	LIP	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 7698E	Veh. Inspected	SNA 2413H	
	Policy No.	-	Coverage	0	
	Claim No.	AVS24/3367	Excess	\$0.00	
	Assign From	CMPU	Assign Date	18/11/2024	
2. Vehicle Details					
	Make & Model	TOYOTA PRIUS	C.C	1798	
	Engine No.	2ZR2H37507	Year of Reg.	14/06/2021	
	Chassis No.	JTDKB3FU103093205	Colour	WHITE	
	Odometer	101301 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/65 R15	FIRENZA	5	
	L/H Front Tyre	195/65 R15	FIRENZA	5	
	R/H Rear Tyre	195/65 R15	FIRENZA	5	
	L/H Rear Tyre	195/65 R15	FIRENZA	5	
4.	The state of the s				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	17/10/2024	Inspection Date	19/11/2024	
	Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					