

CARSMITH PRIVATE LIMITED
PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875
 Tel: 9091 0000/ Email: info@carsmith.biz

*Not Authorized
 Mr
 Marcus
 19/11/24
 1/5 @ 800/
 take photo after repair
 2 days*

VEHICLE NO: GBL928L
MAKE & MODEL: TOYOTA HIACE
DOA: 19.08.2024
CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
RAILING BARING	2	\$ 320.00	11 X
REAR FENDER LH	1	\$ 2,745.00	11 X
REAR FENDER INNER LH	1	\$ 3,210.00	11 X
REAR BUMPER	1	\$ 625.00	11 X
TAILGATE	1	\$ 1,365.00	11 X
TAIL GATE LOCK	1	\$ 280.00	11 X
REAR TAIL LAMP LH	1	\$ 640.00	11 X
REAR TAIL LAMP PANEL LH	1	\$ 270.00	11 X

\$ 9,455.00
LESS 25% \$ 945.50
SUB TOTAL \$ 8,509.50

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR RIM LH	1	\$ 500.00	11 X
SIDE DOOR CLIP	1	\$ 50.00	11 X
TAILGATE CLIP	1	\$ 52.00	11 X
JOINT SEALANT	1	\$ 120.00	11 X
SUB TOTAL		\$ 722.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	1	\$ 300.00	20
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	11 X
REMOVE AND REFIT AND RENEW REAR EXHAUST	1	\$ 150.00	11 X
REMOVE AND REFIT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 300.00	11 X
PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 900.00	220
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1	\$ 900.00	300
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	1	\$ 100.00	11 X

SUB TOTAL \$ 2,770.00

GRAND TOTAL \$ 12,001.50

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P. 625
 252
 468.75
 540
 1008.75
 202
 807