

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INC 24/10370/UVH3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: G3L 928Lat Workshop m/s Corsmith

of _____

Insured: SMN 3589X

Policy No. _____

Claims No. MT/1291647-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 886L

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

LT 14 25030Veh No: G3L 928L Yr Regn: 18/03/24Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (A) DX2-8Make: Toyota hiace c.c. 2754Colour: Shm A/C: Insured / Std / NI / NASp.Reading: 158819 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GDM 201/055356Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195-R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/08/24 D.O.I. 19/11/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
25/10/24	2/5 \$ 800 informed Alex (red 11,201.50, 93%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 2

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$) S + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format : _____

Lump Sum / I.B.I.: (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	841H
Vehicle Details	
Vehicle No.:	GBL928L
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 2.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	1GD8686783
Chassis No.:	GDH2011055356
Maximum Power Output:	-
Open Market Value:	\$32,385.00
Original Registration Date:	18 Mar 2021
First Registration Date:	18 Mar 2021
Transfer Count:	1
Actual ARF Paid:	\$1,620.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Mar 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$39,589.00
COE Rebate Amount:	\$25,030.00
Total Rebate Amount:	\$25,030.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 19 Nov 2024

OK



Toyota Hiace
2.8A DX

\$90,988

Instl. \$1,316

/mth

\$14,380 /yr

1 Owner Diesel

19-Mar-2021

(6yrs 3mths COE left)

N.Air 2,754 cc



This 1 owner unit are very well taken care by previous owner, almost new condition, very low usage. Smooth engine and gearbox in healthy condition. 100% accident free. Enjoy lifetime servicing and unlimited mileage warranty. Bank/high loan with attractive rate. Trade in are welcome. Ready to handover condition. Contact us for viewing or test drive appointment now.

ABS Bus Pte Ltd|Posted 16-Nov-2024

☐ Compare

PREMIUM AD



Toyota Hiace 2.0A
DX

\$81,988

Instl. \$1,102

/mth

\$11,820 /yr

2 Owners

26-Oct-2021

(6yrs 11mths COE left)

N.Air 1,998 cc



1 owner unit! Well taken care of by previous owner! Low mileage unit! Value for money! Powerful engine with auto gearbox! Auto LED headlight unit! Enjoy lifetime servicing and unlimited mileage warranty! We take in high trade in for your current unit! High loan available with immediate approval! Call now to secure and view this unit now!

ABS Bus Pte Ltd|Posted 15-Nov-2024

☐ Compare

PREMIUM AD



★ StarAd View All

2023 Toyota Alphard 2.5 S C-Package.

Original Factory Condition, One Owner Unit, Low Mileage. 88 Auto Pte Ltd

Lake View Credit Pte Ltd

THREE DECADES OF INTEGRITY & PASSION

FIND OUT MORE

Republic Auto



Toyota Hiace 2.0A
DX

\$80,988

Instl. \$1,088

/mth

\$11,640 /yr

1 Owner

03-Nov-2021

(6yrs 11mths COE left)

N.Air 1,998 cc



1 owner. Low mileage. Lifetime servicing and 2 years warranty unlimited mileage until this vehicle is sold or scrap! and free \$600 workshop voucher and 4% insurance rebate and many more great deal! Well maintained by previous owner, buy with peace of mind and save your future money! Offer high trade in! Full loan available and 100% loan guaranteed approve

ABS Bus Pte Ltd|Posted 15-Nov-2024

☐ Compare

PREMIUM AD



Toyota Hiace 2.8A
DX

\$85,800

Instl. \$1,284

/mth

\$13,990 /yr

1 Owner Diesel

07-Jan-2021

(6yrs 1mth COE left)

N.Air 2,754 cc



1 owner! Diesel unit! Come with checker plate! Class 3A drivable! 5 doors for loading / unloading! One of the cheapest in the market! Trade in are welcome! Flexible financial package! Call / WhatsApp our sales personnel contact below for further viewing / discussion now!

Car (S) Pte Ltd|Posted 11-Nov-2024

☐ Compare

PREMIUM AD

CARSMITH PRIVATE LIMITED

PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875

Tel: 9091 0000/ Email: info@carsmith.biz

Not Authorized
in
Meru 3
19/11/24
1/5 @ 800
take photo. the rep
2 days

VEHICLE NO: GBL928L

MAKE & MODEL: TOYOTA HIACE

DOA: 19.08.2024

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
RAILING BARING	2	\$ 320.00	11 X
REAR FENDER LH	1	\$ 2,745.00	R X
REAR FENDER INNER LH	1	\$ 3,210.00	11 X
REAR BUMPER	1	\$ 625.00	gross
TAILGATE	1	\$ 1,365.00	11 X
TAIL GATE LOCK	1	\$ 280.00	11 X
REAR TAIL LAMP LH	1	\$ 640.00	11 X
REAR TAIL LAMP PANEL LH	1	\$ 270.00	11 X

\$ 9,455.00
LESS 25% \$ 945.50
SUB TOTAL \$ 8,509.50

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR RIM LH	1	\$ 500.00	11 X
SIDE DOOR CLIP	1	\$ 50.00	11 X
TAILGATE CLIP	1	\$ 52.00	11 X
JOINT SEALANT	1	\$ 120.00	11 X
SUB TOTAL		\$ 722.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	1	\$ 300.00	20
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	11 X
REMOVE AND REFIT AND RENEW REAR EXHAUST	1	\$ 150.00	11 X
REMOVE AND REFIT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 300.00	11 X
PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 900.00	220
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1	\$ 900.00	300
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	1	\$ 100.00	11 X

SUB TOTAL \$ 2,770.00

GRAND TOTAL \$ 12,001.50

- LKK Auto Consultants hence notify the Repairer of the following:
- To survey before/after spray painting
 - To display damaged part(s) before survey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 625
252
468.75
540
1008.75
202
807