

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : MT/1303520-004 Date: 09th Dec 2024

Our Ref : CS/INC24110372/Avh3e2

M/s Income Insurance Ltd

75 Bras Basah Road Income Centre Singapore 189557 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO. SJM 1608D INSURED VEHICLE NO. GBK 2116E ACCIDENT ON 08/11/2024

Instruction was received to inspect the vehicle Reg. No. SJM 1608D. The inspection was conducted on 08/11/2024 at the premises of M/s N-51 Automotive Pte Ltd, 2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921.

The following vehicle information was recorded:

Registration Number : SJM 1608D

Make/Model : Suzuki SX4 S-Cross 1.6 CVT 4WD S/R

Year of Registration : 2017 Body Colour : Green

Chassis Number : TSMJYB22S00417421

Engine Capacity : 1598 cc

The vehicle sustained damages at the front and rear portion. (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**Total Loss**".

Market Value S\$ 40,000.00 (est)

Less: LTA Reimbursement Value (RV) (S\$ 26,082.00)

Nett Liability S\$ 13,918.00

==========

Vehicle Inspected By:

ADRIAN LING WAI PING

B. Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.