

Name & Address:

Motor Claims Department
FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Vehicle No:

SLK409E

Date:

18-Nov-24

Brand & Model:

BMW IX3 M Sport Inspiring

Franchise:

BMW

Email/Fax No:

Contact No:

Chassis/VIN No:

WBY42DU060SC04577

Contact Person (Eurokars):

JOBI

Type of Claim:

OWN DAMAGE

YEAR MODEL:

23/11/2023

WIP#:

30459

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER X	51 12 5A47A34	1		-	\$ 1,629.75
2	KIT ADD-ON X	51 12 5B688B5	1		-	\$ 46.80
3	LOWER BUMPER TRIM (GLOSSY BLACK) X R (try ph)	51 12 5A47A49	1		-	\$ 304.55
4	LOWER SPOILER (FROZEN GREY) (Silk) - cut	51 12 9850837	1		-	\$ 287.15
5	COVER, BOTTOM LH (I-BLUE) X	51 12 9850849	1		-	\$ 91.90
6	SIDE MOUNT BUMPER LH X	51 12 9853316	1		-	\$ 229.30
7	REAR MOUNT, BUMPER LH X	51 12 9850833	1		-	\$ 129.80
8	ADAPTER FOR REAR BUMPER X MC	51 12 9850847	1		-	\$ 177.55
9	EXPANDING RIVET / MC	07 14 7401727	6		-	\$ 16.20
10	EXPANDING RIVET / MC	51 77 7171004	18		-	\$ 27.00
11	REFLECTOR LH X	63 14 8083833	1		-	\$ 43.50
12						\$ -

Sub-Total (Parts Price) \$ - \$ 2,983.50

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	850	\$ 1,700.00
2	TO RESPRAY REAR BUMPER.	X	\$ 1,500.00
3	TO TRANSFER THE REVERSE SENSORS.	nett X	\$ 500.00
4	TO ISOLATE THE EV BATTERY DURING THE REPAIRS INCLUDING CHARGING OF BATTERY	nett X	\$ 250.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett 350	\$ 500.00
7	SUNDRIES.	nett X	\$ 50.00

Survey Date & Time:

Repair Days:

Excess:

Surveyor Remarks: m n p/p m Bo L m

Sub-Total (Labour Price) \$ - \$ 4,750.00

	REVISED	PRICE
Parts Price	\$ -	\$ 2,983.50
Labour Price	\$ -	\$ 4,750.00
Total (Initial Estimate)	\$ -	\$ 7,733.50
Supp 1	\$ -	\$ -

REPAIR ESTIMATE

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	-	\$	7,733.50
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	7,733.50
GST	9%	\$	-	\$ 696.02
GRAND TOTAL		\$	-	\$ 8,429.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____