

REPAIR ESTIMATE

DARTS / MATERIAL CHARGES			MARK - Survey Marking [Key "A" if item is approved
OWN DAMAGE	23/11/2023	30459	6331 0680
Type of Claim:	YEAR MODEL:	WIP#:	Contact No (Eurokars):
		WBY42DU060SC04577	JOBI
Email/Fax No:	Contact No:	Chassis/VIN No:	Contact Person (Eurokars):
SINGAPORE 068877		BMW iX3 M Sport Inspiring	BMW
#16-01 CITY HOUSE		DNAVA WO AA Co aat la agisig a	DN 4147
36 ROBINSON ROAD		Brand & Model:	Franchise:
Motor Claims Department FIRST CAPITAL INSURANCE LTD		SLK409E	18-Nov-24
Name & Address:		Vehicle No:	Date:

PARTS / MATERIAL CHARGES MARK = Survey Marking [Key "A" if item is approved]								
NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED		PRICE	
1	REAR BUMPER	51 12 5A47A34	1				\$	1,629.75
2	KIT ADD-ON	51 12 5B688B5	1				\$	46.80
3	LOWER BUMPER TRIM (GLOSSY BLACK)	51 12 5A47A49	1				\$	304.55
4	LOWER SPOILER (FROZEN GREY)	51 12 9850837	1		\$	287.15	\$	287.15
5	COVER, BOTTOM LH (I-BLUE)	51 12 9850849	1				\$	91.90
6	SIDE MOUNT BUMPER LH	51 12 9853316	1				\$	229.30
7	REAR MOUNT, BUMPER LH	51 12 9850833	1				\$	129.80
8	ADAPTER FOR REAR BUMPER	51 12 9850847	1				\$	177.55
9	EXPANDING RIVET	07 14 7401727	6		\$	16.20	\$	16.20
10	EXPANDING RIVET	51 77 7171004	18		\$	27.00	\$	27.00
11	REFLECTOR LH	63 14 8083833	1				\$	43.50
12							\$	-

Sub-Total (Parts Price) \$ 330.35 \$ 2,983.50

LABOUR / SERVICES CHARGES						
NO	DESCRIPTION REVISED			PRICE		
1	TO REMOVE /REPLACE REAR BUMPER AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$	850.00	\$	1,700.00	
2	TO RESPRAY REAR BUMPER.			\$	1,500.00	
3	TO TRANSFER THE REVERSE SENSORS.			\$	500.00	
4	TO ISOLATE THE EV BATTERY DURING THE REPAIRS INCLUDING CHARGING OF BATTERY			\$	250.00	
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$	150.00	\$	250.00	
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$	350.00	\$	500.00	
7	SUNDRIES.			\$	50.00	

Survey Date & Time:	Repair Days:	Excess:	Sub-Total (Labour F	rice) \$	1,350.00	\$ 4,750.00
					REVISED	PRICE
Surveyor Remarks:			Parts Price	\$	330.35	\$ 2,983.50
			Labour Price	\$	1,350.00	\$ 4,750.00
			Total (Initial Estimate)	\$	1,680.35	\$ 7,733.50
			Supp 1	\$	-	\$ -



REPAIR ESTIMATE

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Supp 2		\$ -	\$ -
Supp 3		\$ -	\$ -
Total (Before Excess)		\$ 1,680.35	\$ 7,733.50
Less Excess		\$ -	\$ -
TOTAL (After Excess)		\$ 1,680.35	\$ 7,733.50
GST	9%	\$ 151.23	\$ 696.02
GRAND TOTAL		\$ 1,831.58	\$ 8,429.52