



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110374/Aqh3e2
75 BRAS BASAH ROAD	Date:	23/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJA 1121D	Veh. Inspected	SKP 3664A
Policy No.	-	Coverage	0
Claim No.	MT/1304171-002	Excess	\$0.00
Assign From	AZHARI AFIDI	Assign Date	19/11/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ C180K	C.C	1597
Engine No.	27191031343250	Year of Reg.	18/03/2011
Chassis No.	WDD2040452A511756	Colour	BRONZE
Odometer	182697 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45 R17	ATLANDER	6
L/H Front Tyre	225/45 R17	ATLANDER	6
R/H Rear Tyre	225/45 R17	ATLANDER	6
L/H Rear Tyre	225/45 R17	ATLANDER	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/11/2024	Inspection Date	19/11/2024 (15:55)
Survey held at	N-51 AUTOMOTIVE PL - 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days