

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0869/2024/KS
DATE : 19-Nov-24
WIP : 38944

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/11/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MDM LIEW KUEY HIONG
ADDRESS : 10A LORNIE ROAD
SINGAPORE 298728

TELEPHONE : HP +65 96826575
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7240107094
VEHICLE NO : SMS 160 S
MODEL CODE : AUDI Q4 SPORTBACK 45 E-TRON
MODEL YEAR : 27/6/2024
ENGINE NO : EDFA
CHASSIS NO : WAUZZZFZ2RP072097
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Nov-24
PLACE OF ACCIDENT : SHEARES SLIP ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 160 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	/
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>EV-610</i>	\$	2,000.00	620
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS. <i>200 x 2</i>	\$	3,500.00	400
4	TO DE-ENERGEISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION.	S/N \$	480.00	/
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	/
TOTAL LABOUR CHARGES		:	\$ 6,632.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 160 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER - UPPER X nn	1	\$ 1,178.00		
2	REAR BUMPER FIXING PARTS ? x nn	1	\$ 204.00		
3	REAR BUMPER TRIM - SATIN BLACK ? X nn	1	\$ 264.00		
4	REAR BUMPER - LOWER <i>hmm</i> ? x nn	1	\$ 956.00		
5	REAR BUMPER SPOILER - SELENITE SILVER / mis	1	\$ 307.00 /	245.60	
6	REAR SPOILER TOWING COVER - SELENITE SILVER X nn	1	\$ 62.00		
7	REAR BUMPER CABLE HOLDER ? x nn	1	\$ 13.00		
8	REAR BUMPER SECURING STRIP / mis	4	\$ 106.00 /	84.80	
9	REAR BUMPER SECURING STRIP / mis	2	\$ 53.00 /	42.40	
10	REAR BUMPER DAMPING X nn	2	\$ 53.00		
11	REAR CONTROL UNIT RETAINER / mis	1	\$ 54.00 /	42.72	
12	REAR LID OPENING CONTROL UNIT / cut	1	\$ 554.00 /	443.20	
13	REAR LID OPENING SENSOR LINE / cut	1	\$ 244.00 /	194.80	
14	AERIAL FOR (KESSY) X nn	1	\$ 84.00		
15	REAR PARKING AIR SENSOR X nn	2	\$ 572.00		
16	REAR PARKING AIR SENSOR SEAL RING / <i>pc</i>	4	\$ 57.00		
17	REAR BUMPER WIRING SET / <i>TN</i>	1	\$ 277.00 /	221.60	
18	REAR REINFORCEMENT BEAM X nn	1	\$ 1,248.00		
19	REAR BUMPER GUIDE SECTION - CENTER X nn	1	\$ 96.00		
20	REAR BUMPER GUIDE PROFILE - LH / RH X nn	2	\$ 132.00		
SUB TOTAL SPARE PARTS		:	\$ 6,514.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 160 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	REAR BUMPER GUIDE SECTION - LH / RH X nn	2	\$ 206.00	
22	REAR WHEEL ARCH COVER - LH / RH / MC	2	\$ 1,284.00 / 1026.40	
23	REAR UNDERBODY TRIM / BR	1	\$ 193.00 / 154.40	
24	SUNDRIES x nn		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 8,697.00	
TOTAL LABOUR CHARGES		:	\$ 6,632.00	
GRAND TOTAL		:	\$ 15,329.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Steve CLKK)
SURVEYED DATE : 20/11/24, 4.30 pm
AUTHORISED DATE :
EXCESS COST : 00 - 1101 HL
LIABILITY :
REMARKS : EXcess - ?
PIP, by BL sy, 3 days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT