



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR MANIVANNAN HARISH KUMAR
BLK. 325A SUMANG WALK
#14-981 SINGAPORE 821325

POLICY NO : THIRD PARTY CLAIM
YOUR REF : SLA 5336 B (LIBERTY)
OUR REF : TP 6731
VECHICLE NO : SNN 8695 C
MAKE/MODEL : TOYOTA SIENTA
DATE OF ACCIDENT : 16.11.24

SURVEY BY

DATE : 18.11.24

- 1 PC TAILGATE
- 1 PC TAILGATE "HYBRID" EMBLEM
- 1 PC TAILGATE TOP LOCK
- 1 PC TAILGATE WEATHERSTRIP
- 1 PC REAR BUMPER
- 1 PC REAR END PANEL *a photo*

S\$ 2,025.90 *bt*
174.00 *acc*
647.90 *X nn*
465.30 *X nn*
1,302.80 *de*
660.50 *Rp*
S\$ 5,276.40 *3502.70*
1,319.10
S\$ 3,957.30 *2627.02*

LKK Auto Consultants hence notify **LESS** 25%
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:

- 1 PC TAILGATE GLASS SEALANT
- 1 SET REAR BUMPER CLIPS
- 1 SET REVERSE SENSOR

S\$ *acc* 60.00 S/ NETT
acc 28.00 "
200 RW/400.00 "
S\$ 488.00 *288*

TO TRANSFER TAILGATE FITTING

S\$ 100.00 *60*

TO REMOVE AND REFIX TAILGATE GLASS

140.00 *120*

TO TRANSFER REVERSE CAMERA

60.00 *30*

TO DISMANTLE AND REFIX REVERSE SENSOR

288

50.00 *30*

TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL

1080

100.00 *40*

LABOUR CHARGES

2627.02
288
1080
\$3995.02

700.00 *500.400*

TO PUTTY AND SPRAY PAINTING CHARGES

04 days

700.00 *600.400*

S\$ 6,295.30

SIN DOLLARS: SIX THOUSAND ONE HUNDRED NINTY-FIVE AND CENTS THIRTY ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

Tanfhir 97445749/62563561
wp 20/11/24 e 1145
tanfhir @ lkh and on
4-5 days p/p Resurvey before part