

LEANG AUTOMOTIVE
BLK 1 KAKI BIKIT AVE 6 #01-68
AUTOBAY S'PORE 417883 HP 90286516

not Authorized
der
meraus
20/11/24
4300
4 days

VEHICLE No: SMK 416Y

1PC	REAR SLIDING DOOR O/S	pp/berf	4031	\$4,550.00
1PC	REAR SLIDING DOOR FRAME STICKER O/S	der	fo	\$100.00
1PC	REAR SLIDING DOOR INNER RUBBER O/S	11		\$220.00
1PC	REAR FENDER O/S	R		\$3,800.00
				\$8,670.00
			LESS 10%	\$7,803.00

S.NETT

1SET	REAR DOOR WRAP STICKER O/S	der	\$600.00	400
1SET	REAR FENDER WRAP STICKER O/S	der	\$600.00	400

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	X
TO DISMANTLE & REFIX REAR FENDER GLASS O/S	\$150.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	X
TO SPRAY RUST PROOFING	\$80.00	30
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$900.00	400
TO PUTTY & SPRAY PAINTING	\$680.00	500
TOTAL	\$11,063.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-4111
100
3699.90
fo
950
5449.9
282
4359