



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110389/Dnh3m4
75 BRAS BASAH ROAD	Date:	10/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 7604G	Veh. Inspected	SLQ 561R
Policy No.	-	Coverage	0
Claim No.	MT/1304333-002	Excess	\$0.00
Assign From	JULIE	Assign Date	19/11/2024

2. Vehicle Details

Make & Model	HONDA FREED	C.C	1496
Engine No.	LEB5549841	Year of Reg.	27/06/2017
Chassis No.	GB71025065	Colour	GREY
Odometer	109299 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	YOKOHAMA	5
L/H Front Tyre	205/55R16	YOKOHAMA	5
R/H Rear Tyre	205/55R16	YOKOHAMA	5
L/H Rear Tyre	205/55R16	YOKOHAMA	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/11/2024	Inspection Date	20/11/2024 (10:43)
Survey held at	ALFRED AUTO SERVICES & SUPPLIES BLK 5035 ANG MO KIO 3 #01-355 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days