



HxGN EAM

Accident Report

User	ARIFMS@SBSTRANSIT.COM.SG
Report Created	Nov 27, 2024

EAM

Accident Report



Certificate of Bus Repair

Depot	BN	Bus No	SBS3650E
Driver	70309	Accident Date	Nov 15, 2024
Work Order No	1635771	Case No / AR No	24042 / AR-2024-6236

Date IN	Nov 21, 2024	Date Out	Nov 21, 2024
---------	--------------	----------	--------------

Registration Date	Model/Manufacturer	Chassis No.
Sep 13, 2013	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P929DA162172

Stock Code	Description	Quantity	Total Material Cost (S\$)
30750009 N	SIDE SHEETMETAL PANEL N	1	\$407.61
30750064 N	SIDE SHEETMETAL PANEL N	1	\$1,237.79

TOTAL FOR PARTS		S\$	1,645.40
-----------------	--	-----	----------

S/N	Labour / Spray Painting / Contractor Cost	Amount
1	Workshop Labour	S\$ 188.00
2	Contractor's Repair Charges	S\$ 500.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST		S\$ 688.00
Repair cost of Advertisement / Livery		S\$ 0.00
TOTAL DAMAGE		S\$ 2,333.40
Overheads		S\$ 700.02
Towing Charges		S\$ 0.00
Repair Period : 2.00 Days	Loss of Use	S\$ 917.04
TOTAL LOSS		S\$ 3,950.46