



Accident Reference & Bus No: **AR-2024-6236 – SBS3650E with SJB4761G**

Activated date: Tuesday 19/11/2024 1:51 pm

Activated by: Chong Kee Lim <chongkeelim@sbstransit.com.sg>

Name of Surveyor: *Steve Chen*

Company Name: LKK Surveyor

Date Surveyed: 27/11/2024 ✓ *11.30 am*

Require

Resurvey 1 Date:

Resurvey 2 Date:

Final Endorsement by Surveyor: *[Signature]*

RHS No.1 Wheel arc panel ✓ *Bi*

RHS No.2 Panel ✓ *Bi*

*update
prior to
1/12/24*

steve.chen@lkkauto.com

Estimate (before GST) for

- ☐ Parts cost: **\$ TBA**
- ☐ Contractor Labour cost: **\$ 500** ✓
- ☐ Workshop Labour cost: **\$ 188.00** ✓
- ☐ Advertisement Cost: **\$ 0.00**
- ☐ Repair period: **2 days** ✓

Part by Part

- ☐ Tow Cost: **\$ 0.00**
- ☐ Loss of use: **Not required by surveyor**
- ☐ Overheads: **Not required by surveyor**

arif - 8481 0499

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company