



HxGN EAM

Accident Report

User ARIFMS@SBSTRANSIT.COM.SG

Report Created Nov 27, 2024

EAM

Accident Report



Certificate of Bus Repair

Depot	BN	Bus No	SBS3650E
Driver	70309	Accident Date	Nov 15, 2024
Work Order No	1635771	Case No / AR No	24042 / AR-2024-6236

Date IN Nov 21, 2024 **Date Out** Nov 21, 2024

Registration Date	Model/Manufacturer	Chassis No.
Sep 13, 2013	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P929DA162172

Stock Code	Description	Quantity	Total Material Cost (\$\$)	
30750009 N	SIDE SHEETMETAL PANEL N	1	\$407.61	/ DD
30750064 N	SIDE SHEETMETAL PANEL N	1	\$1,237.79	/ DD

	TOTAL FOR PARTS	\$\$	1,645.40
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	Workshop Labour	\$\$	188.00
2	Contractor's Repair Charges	\$\$	500.00
	TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST	\$\$	688.00
	Repair cost of Advertisement / Livery	\$\$	0.00
	TOTAL DAMAGE	\$\$	2,333.40
	Overheads	\$\$	700.02
	Towing Charges	\$\$	0.00
Repair Period : 2.00 Days /	Loss of Use	\$\$	917.04
	TOTAL LOSS	\$\$	3,950.46