(08/11/13) wef ASS, REC. BY: Marcus REF: CS/LP	c241/0394/4063
ASSI	GNMENT
From: Date:	Veh No: GBG 58556 Yr Regn: 08/49/17
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TPV WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or (M)
To Inspect Vehicle No: GBGSTG	Make: Toyoto higel c.c 2982
at Workshop m/s	Colour Silve A/C: Insured / Std / NI / NA
of	Sp.Reading 227933 T/Radio: Insured / Std / NI / NA
Insured: 6 B(c 33276	Eng/No:
Policy No.	C/NO: JTFH TOZP 800233295
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi : Nil / S/Rim / STD A/Rim or
	Tyre Size: F: / P5 n (5
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or hetw.
Bal. or Market Value: 436k.	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: 6 days Res.: Yes or No	D.O.A. 18/11/24 D.O.I. 20/11/24
Lum Sum: 23 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS C767 Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: L1A 8 8688	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction Dc / 134.	
Disnorth 22-11-24@ 10.25am	
28/11/24 1/5 \$ 5-300 informal Ken	(Red \$ 518h. 53, 499)
28/11/10 1/5 & 2300 inhound then	ny (100) (11.)
	1
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1)03/12 MMH : Final Report	Resurvey No. of Trip: 2 Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee	: Site Insp (\$)S+RS,St
	: Interview (\$) Photos
Report Format: 7/P Lump Sum / I.B.I. (\$ 5300)	: Tech. Invs (\$) Others
Lump Sum / I.B.I. (\$ 5300)	:Weekend (\$
	TOTAL

BLUWEL AUTOMOTIVE SERVICE PTE LTD 1 KAKI BUKIT AVE 6 # 01-28/53/55/56 SINGAPORE 417883 TEL :67452088

VEHICLE No: GBG 5855G

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Not Authorial

20/11/24

1/2 \$ 5300 ahphe Ales rejains 6 days.

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

1PC	TAILGATE Body 20 , Date:		\$2,254.20
1PC	TAILGATE OUTER GARNISH 300 % /C/0		\$306.50
1PC	TAILGATE INNER LOCK Dayse		\$399.50
1PC	TAILGATE REAR LOGO		\$78.00
1PC	TAILGATE 'HIACE' STICKER NEW KIN		\$58.00 X
	TAILGATE 'TOYOTA' STICKER W (\$80.00 X
1PC	TAILGATE POTOTA STICKER		\$1,720.30 🔾
1PC	TAILGATE WEATHERSTRIP 1~1		\$399.20
1PC	TAILGATE WEATHERSTRIP		\$311.20
1PC			\$904.60 120
2PCS	TAILLY IVII 3 G \$ 132.133		\$151.20
1PC	17112271111		\$68.00
1PC	TAILLAMP LOWER GARNISH BRACKET N/S CAL		
1PC	TAILLAMP HOUSING PANEL N/S		\$545.20 X
1PC	RAER BUMPER DIS/13.2		\$618.60
2PCS	REAR BUMPER SIDE HOLDERS @\$105.00 N/s Cre O/Syn		\$210.00 126
2PCS	REAR BUMPER LOWER BRACKETS @\$65.00 544		\$130.00 —
1PC	REAR END PANEL OUTER DO / 36+		\$439.70
1PC	REAR END PANEL INNER		\$818.60
1PC	REAR END PANEL TOP PLATE		\$222.70₺
	300		\$9,715.50
		LESS 25%	\$7,286.53

S.NETT

REAR WINDSCREEN SEALANT	\$50.0040 3/70
REAR WINDSCREEN INNER SEAL LAN	\$50.00 20 5/2
TAILGATE 70Km/h STICKER	\$20.00/0 5/2
REAR LICENCE PLATE SX	\$50.00 ×
REAR BUMPER CLIPS MM	\$50.00 30 5/N
REAR BUMPER REVERSE SENSOR CM	\$450.00 200 5/N
	REAR WINDSCREEN INNER SEAL AM TAILGATE 70Km/h STICKER REAR LICENCE PLATE SU REAR BUMPER CLIPS

TO CHECK WIRING redead	\$50.00 20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00 30
TO DISMANTLE & REPLACED REAR WINDSCREEN	\$120.00
TO TRANSFER TAILGATE MECHANISM	\$100.00 60
TO SPRAY RUST PROOFING	\$100.00 <i>6</i> o
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00 850
TO PUTTY & SPRAY PAINTING	\$1,080.00 900
	70TAC \$10, 48.53


9.8713.4 4285.05 300

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	787K
Vehicle No.:	GBG5855G
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2750128
Chassis No.:	JTFHT02P800233295
Maximum Power Output:	•
Open Market Value:	\$28,138.00
Original Registration Date:	08 Sep 2017
First Registration Date:	08 Sep 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$1,407.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	07 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$31,040.00
COE Rebate Amount:	\$8,688.00
Total Rebate Amount: Message	\$8,688.00

The information contained herein is correct as at 20 Nov 2024



Compare