



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 ATTN: JANICE KOH			Ref: CS/AGI24110398/Avp3e2(N) Date: 03/04/2025 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLN 8251Z	Veh. Inspected	SLC 8004D
	Policy No.	P10561282R03	Coverage (\$)	0.00
	Claim No.	C10032942/JK	Excess (\$)	0.00
	Assign From	JANICE KOH	Assign Date	19/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 6	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JM6GJ1072G0232636	Colour	BLACK
	Odometer	122157 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	245/45 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	245/45 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	245/45 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/11/2024	Inspection Date	02/12/2024
	Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	