

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Not Authorized

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3162/11/24 Your Ref: _____ Date: 20th NOV 2024

MR ANG GEE HUI, JASON
BLK 632B, #08-661,
Punggol Drive, S(822632)

4 days

new means
20/11/24

1/2 of \$4000
Theph. Huang

Estimate cost of repair to SUZUKI SX4 (A) 1.6 H/B - SJQ 7197 L

1 pc front bonnet	R	\$ 1,299.90 X
1 pc front bonnet n/s hinge	11	67.60 X
1 pc n/s head lamp assy	one	784.60
1 pc n/s head lamp bracket	11	38.00 X
1 pc front n/s fender	Bent	67.60 921.90
1 pc front n/s fender inner shield	to in	157.00
8 pcs front n/s fender inner shield clips	mu	40.00
1 pc front n/s fender wheel guard	grand	162.00
10 pcs front n/s fender wheel guard clips	11	50.00 X
1 pc front n/s fender 'VVT' emblem	mu	32.00
1 pc n/s head lamp panel	Bent/mu	182.00
1 pc front bumper	cut/mu	790.48 863.40
10 pcs front bumper clips	mu	50.00
1 pc front bumper n/s side retainer	one	38.00
1 pc front bumper reinforcement	R	279.00 X
1 pc front bumper n/s side bracket clips	11	10.00 X
1 pc front bumper n/s fog lamp garnish	grove	99.10
1 pc front bumper n/s side garnish	grove	66.90
1 pc front bumper centre lower garnish	cut/mu	175.00
1 pc front bumper n/s fog lamp assy	one	287.40
1 pc front n/s sport rim	R	620.00 X
		\$ 6,223.80
		Less 15% \$ 933.57
		\$ 5,290.23

To wiring check up & adjust headlight alignment. 50.00 30

To check & adjust front wheel alignment & balancing. 150.00 60

To respray Tuff-Kote on all affected accident parts. 120.00 50

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, front n/s door & necessary parts, to weld, renew & align above parts. 1,800.00 800

To putty & respray painting on all affected accident parts. 1,800.00 1100

\$ 9,210.23

=====

Dollars : Nine Thousand Two Hundred Ten Dollars And Cents Twenty Three Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-348-48
112
2962.64
2040
5002.64
400